ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
D19-6_D19-5		Oliver Springs		Sleepy Hollow	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH		Total I	Length	Year Laid	Sha	ape	Location	n Details	
D1	D19-6		5.3		Circ	ular			
DS Ma	DS Manhole		surveyed	Year Renewed	Height	Width	Pipe Joint		
D1	D19-5		5.3		8	8	4		
SPR	N/A	MPR	15	PO Number		Pre-F			
0001	-	MADDI		4397-03					
SPRI	N/A	MPRI	2.1	Work Order					
QSR	N/A	QMR	3126	4397-02				urvey	
OF	PR	Surveyed By		Direction	Date		Media label		
1	5	Barry_Rogers		Downstream	2015	20150630			
OF	PRI	Certificate Number		Pre-Cleaning	Tir	Time			
2.1		U-1012-16405		Jetting	10:16		Damp		
	Date Cleaned					End Time		Additional Info	
	20150630					10:27			

Distance	Condition	O Df1	Values			1-1-4	Clock Position		0
	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	D19-5(D19-6)								
0.0 ft.	Water Level				5				
6.0 ft.	Water Level Sag				15				2
9.5 ft.	Tap Break-In		6		0		3		
41.6 ft.	Tap Break-In		6		0		9		
50.9 ft.	Deposits Attached Other				15		7		3
61.9 ft.	Water Level Sag				15				2
106.2 ft.	Water Level Sag				20				2
127.0 ft.	Deposits Attached Other				10		7		2
186.5 ft.	Water Level Sag				10				2
190.2 ft.	Tap Factory Made		6		0		10		
200.3 ft.	Water Level Sag				20				2
223.2 ft.	Water Level				10				
225.3 ft.	Access Point Manhole				0				
Remarks:	D19-4(D19-5)			•	•		'		•





Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-6_D19-5	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
D19-6	225.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-5	225.3		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: D19-5(D19-6)



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 6.0 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 9.5 ft. Grade: 0

Condition: Tap Break-In

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-6_D19-5	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
D19-6	225.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-5	225.3		8	8	4	



Distance: 41.6 ft. Grade: 0

Condition: Tap Break-In


Remarks: N/A



Distance: 50.9 ft. Grade: 3

Condition: Deposits Attached Other


Remarks: N/A



Distance: 61.9 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 106.2 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-6_D19-5	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Sh	Shape		Details
D19-6	225.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-5	225.3		8	8	4	



Distance: 127.0 ft. Grade: 2

Deposits Attached Other

Remarks: N/A

Condition:



Distance: 186.5 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 190.2 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 200.3 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-6_D19-5	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Sh	Shape		Details
D19-6	225.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-5	225.3		8	8	4	



Distance: 223,2 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 225.3 ft. Grade:

Condition: Access Point Manhole

Remarks: D19-4(D19-5)



PACP Conditions

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use
D19-6_D19-5		Oliver Springs		Sleepy Hollow	Concrete F	Pipe (non	Easement/R	Sanitary
Upstrea	Upstream MH		Length	Year Laid	Sh	ape	Location Details	
D19	9-6	22	5.3		Circ	ular		
DS Ma	nhole	Length surveyed		Year Renewed	Height	Width	Pipe Joint	
D19	D19-5		5.3		8	8	4	
SPR	N/A	MPR	15	PO Number	4397-03 Work Order		Customer	
SPRI	N/A	MPRI	2.1	4397-03			GRW	
SFKI	IV/A	IVIFIXI	2.1	Work Order			Purpose e-Rehabilitation Survey	
QSR	N/A	QMR	3126	4397-02				
OF	PR	Surveyed By		Direction	Date		Media label	
1:	5	Barry_Rogers		Downstream	20150630			
OP	OPRI		e Number	Pre-Cleaning	Time		Weather	
2.1		U-1012-16405		Jetting	10:16		Damp	
	Date Cleaned					End Time		nal Info
	20150630					10:27		

	Structural Ratings			0	& M Ratin	gs	Com	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	6	12	2	6	12
	3	0	0	3	1	3	3	1	3
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	0		Subtotals	7		Subtotals	7	
SUMMARY	Struct	ipe Rating ural Index ick Rating	0 0 0000	Pipe Rating 15 O&M Index 2.1 O&M Quick Rating 3126		Overall Pipe Rating Overall Index Ovrl. Quick Rating		15 2.1 3126	