ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use
D19-8_D19-7		Oliver Springs		Sleepy Hollow	Concrete F	Pipe (non	Yard	Sanitary
Upstream MH		Total Length		Year Laid	Shape		Location Details	
D19-8		26	2.2		Circ	cular		
DS Manhole		Length surveyed		Year Renewed	Height	Width	Pipe Joint	
D19-7		262.2			8	8	4	
SPR	3	MPR	4	PO Number		Customer		
2001				4397-03		GRW		
SPRI	3	MPRI	4	Work Order			Purpose	
QSR	3100	QMR	4100	4397-02		Pre-Rehabilitation Surv		Survey
Ol	PR	Surve	/ed By	Direction	Date		Media label	
-	7	Barry_Rogers		Downstream	20150630			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
3.5		U-1012-16405		Jetting	08:13		Damp	
		Date C	leaned	End Time		Additional Info		
		2015	0630		08:43			

Distance	Condition	Cont Diet	Values			laint	Clock Position		Crada
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	D19-7(D19-8)								
0.0 ft.	Water Level				5				
38.7 ft.	Tap Factory Made		6		0		10		
68.3 ft.	Tap Factory Made		6		0		2		
151.0 ft.	Tap Break-In		6		0		2		
191.5 ft.	Hole				0		7		3
192.7 ft.	Tap Factory Made		6		0		10		
245.7 ft.	Tap Factory Made		6		0		2		
260.3 ft.	Tap Factory Made		6		0		10		
262.0 ft.	Water Level				5				
262.1 ft.	Tap Factory Made		8				6		
Remarks:	drop line								
262.2 ft.	Infiltration Runner					✓	8	10	4
Remarks:	drop line								
262.3 ft.	Survey Abandoned				0				
Remarks:	CAN NOT PASS DROPPED INVERT								





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-8_D19-7	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
D19-8	262.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-7	262.2		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: D19-7(D19-8)



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 38.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 68.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-8_D19-7	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	
D19-8	262.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-7	262.2		8	8	4	



Distance: 151.0 ft. Grade:

Condition: Tap Break-In

Remarks: N/A



Distance: 191.5 ft. Grade: 3

Condition: Hole Remarks: N/A



Distance: 192.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 245.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-8_D19-7	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
D19-8	262.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-7	262.2		8	8	4	



Distance: 260.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 262.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 262.1 ft. Grade: 0

Condition: Tap Factory Made

Remarks: drop line



Distance: 262.2 ft. Grade: 4

Condition: Infiltration Runner

Remarks: drop line

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D19-8_D19-7	Oliver Springs	Sleepy Hollow	Concrete Pipe (non		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
D19-8	262.2		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D19-7	262.2		8	8	4	,



Distance: 262.3 ft. Grade: 0

Condition: Survey Abandoned

Remarks: CAN NOT PASS DROPPED INVERT



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
D19-8_D19-7 Oli		Oliver	Springs	Sleepy Hollow	Concrete F	Concrete Pipe (non		Sanitary
Upstre	Upstream MH		Length	Year Laid	Shape		Location Details	
D1	D19-8		2.2		Circ	ular		
DS M	anhole	Length surveyed		Year Renewed	Height Width		Pipe Joint	
D1	D19-7		2.2		8	8	4	
SPR	3	MPR	4	PO Number				
				4397-03		GRW		
SPRI	3	MPRI	4	Work Order			Purpose	
QSR	3100	QMR	4100	4397-02		Pre-Rehabilitation Surve		urvey
0	PR	Surveyed By		Direction	Date		Media label	
	7	Barry_Rogers		Downstream	20150630			
OI	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
3	3.5		2-16405	Jetting	08:13 End Time		Damp	
		Date C	Cleaned	Additional Info				
		2015	60630		08	:43		

	Stru	Structural Ratings			& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	0	0	2	0	0
	3	1	3	3	0	0	3	1	3
	4	0	0	4	1	4	4	1	4
	5	0	0	5	0	0	5	0	0
Code ID Length									
	Subtotals	1		Subtotals	1		Subtotals	2	
SUMMARY	Struct	ipe Rating ural Index ick Rating	3 3.0 3100	0	Pipe Rating 4 Overall Pipe Rating O&M Index 4.0 Overall Index &M Quick Rating 4100 Ovrl. Quick Rating		erall Index	7 3.5 4131	