



Defect Listing

Pipe Segment Refere... D19-9_D19-8	City Oliver Springs	Street Sleepy Hollow	Material Other	Location C... Yard	Sewer Use Sanitary
Upstream MH D19-9	Total Length 174.7	Year Laid	Shape Circular	Location Details	
DS Manhole D19-8	Length surveyed 174.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A

SPR N/A	MPR 2	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 2100		
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150630
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:46
	Date Cleaned 20150630	End Time 08:01	Weather Damp
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D19-9									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
40.7 ft.	Water Level Sag				10	<input type="checkbox"/>			2
74.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
127.1 ft.	Tap Break-In		6		0	<input type="checkbox"/>	9		
172.2 ft.	Water Level				5	<input type="checkbox"/>			
174.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D19-8									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D19-9_D19-8	Oliver Springs	Sleepy Hollow	Other	Yard	Sanitary
Upstream MH D19-9	Total Length 174.7	Year Laid	Shape Circular	Location Details	
DS Manhole D19-8	Length surveyed 174.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D19-9



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 40.7 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A




Distance: 74.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D19-9_D19-8	Oliver Springs	Sleepy Hollow	Other	Yard	Sanitary
Upstream MH D19-9	Total Length 174.7	Year Laid	Shape Circular	Location Details	
DS Manhole D19-8	Length surveyed 174.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A



Distance: 127.1 ft. Grade: 0
Condition: Tap Break-In
Remarks: N/A



Distance: 172.2 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 174.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D19-8



PACP Conditions

Pipe Segment Refere... D19-9_D19-8	City Oliver Springs	Street Sleepy Hollow	Material Other	Location C... Yard	Sewer Use Sanitary
Upstream MH D19-9	Total Length 174.7	Year Laid	Shape Circular	Location Details	
DS Manhole D19-8	Length surveyed 174.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A
SPR N/A	MPR 2	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 2100				
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150630	Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:46	Weather Damp	
Date Cleaned 20150630			End Time 08:01	Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	1	2	2	1	2
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									