



Defect Listing

Pipe Segment Refere... D2-2_D2-1	City Oliver Springs	Street Henley Cir	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH D2-2	Total Length 258.1	Year Laid	Shape Circular	Location Details	
DS Manhole D2-1	Length surveyed 258.1	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR N/A	MPR 2	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 2100		
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150707
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:33
	Date Cleaned 20150707	End Time 14:57	Weather Dry
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D2-2									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
5.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
79.8 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
173.1 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
250.6 ft.	Water Level Sag				15	<input type="checkbox"/>			2
256.6 ft.	Water Level				5	<input type="checkbox"/>			
258.1 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D2-1									




Image Report 4/Page


Pipe Segment Refere... D2-2 D2-1	City Oliver Springs	Street Henley Cir	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH D2-2	Total Length 258.1	Year Laid	Shape Circular		Location Details	
DS Manhole D2-1	Length surveyed 258.1	Year Renewed	Height 8	Width 8	Pipe Joint... 4	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D2-2



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 5.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 79.8 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D2-2 D2-1	Oliver Springs	Henley Cir	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D2-2	258.1		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D2-1	258.1		8	8	4



Distance: 173.1 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 250.6 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Distance: 256.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 258.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D2-1



Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D2-2_D2-1	Oliver Springs	Henley Cir	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D2-2	258.1		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D2-1	258.1		8	8	4
SPR	N/A	MPR	2	Customer	
SPRI	N/A	MPRI	2	GRW	
QSR	N/A	QMR	2100	Purpose	
				Pre-Rehabilitation Survey	
OPR	Surveyed By	Direction	Date	Media label	
2	Barry_Rogers	Downstream	20150707		
OPRI	Certificate Number	Pre-Cleaning	Time	Weather	
2	U-1012-16405	Jetting	14:33	Dry	
Date Cleaned			End Time	Additional Info	
20150707			14:57		

Page #: 4