



Defect Listing

Pipe Segment Refere... D20-12_D20-11	City Oliver Springs	Street Airport rd	Material PolyVinyl Chloride	Location C... Yard	Sewer Use Sanitary
Upstream MH D20-12	Total Length 201.7	Year Laid	Shape Circular	Location Details Off Side of RD	
DS Manhole D20-11	Length surveyed 201.7	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150601	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:41	Weather Damp	
Date Cleaned 20150601			End Time 10:54	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D20-12									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
200.5 ft.	Water Level				5	<input type="checkbox"/>			
201.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D20-11									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D20-12_D20-11	Oliver Springs	Airport rd	PolyVinyl Chloride	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D20-12	201.7		Circular	Off Side of RD	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D20-11	201.7		8	8	13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D20-12



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 200.5 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 201.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D20-11



Pipe Segment Refere... D20-12_D20-11	City Oliver Springs	Street Airport rd	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH D20-12	Total Length 201.7	Year Laid	Shape Circular		Location Details Off Side of RD	
DS Manhole D20-11	Length surveyed 201.7	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150601		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:41		Weather Damp	
Date Cleaned 20150601			End Time 10:54		Additional Info	

Page #: 3