



Defect Listing

Pipe Segment Refere... D20-13_D20-12	City Oliver Springs	Street Airport Road	Material PolyVinyl Chloride	Location C... Yard	Sewer Use Sanitary
Upstream MH D20-13	Total Length 127.3	Year Laid	Shape Circular	Location Details Side of Road	
DS Manhole D20-12	Length surveyed 127.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR 2	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 2100				
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150601	Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:23	Weather Damp	
Date Cleaned 20150601			End Time 10:34	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D20-13									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
124.6 ft.	Deposits Settled Fine				5	<input type="checkbox"/>	5	7	2
125.0 ft.	Water Level				5	<input type="checkbox"/>			
127.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D20-12									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D20-13_D20-12	Oliver Springs	Airport Road	PolyVinyl Chloride	Yard	Sanitary
Upstream MH D20-13	Total Length 127.3	Year Laid	Shape Circular	Location Details Side of Road	
DS Manhole D20-12	Length surveyed 127.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D20-13



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 124.6 ft. Grade: 2
Condition: Deposits Settled Fine
Remarks: N/A



Distance: 125.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D20-13_D20-12	Oliver Springs	Airport Road	PolyVinyl Chloride	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D20-13	127.3		Circular	Side of Road	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D20-12	127.3		8	8	13



Distance: 127.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D20-12



Pipe Segment Refere... D20-13_D20-12	City Oliver Springs	Street Airport Road	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH D20-13	Total Length 127.3	Year Laid	Shape Circular		Location Details Side of Road	
DS Manhole D20-12	Length surveyed 127.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR 2	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose		
QSR N/A	QMR 2100			Pre-Rehabilitation Survey		
OPR 2	Surveyed By Barry_Rogers	Direction Downstream	Date 20150601		Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:23		Weather Damp	
Date Cleaned 20150601			End Time 10:34		Additional Info	

[illegible]