



Defect Listing

Pipe Segment Refere... D20-6_D20-5	City Oliver Springs	Street Airport Rd	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH D20-6	Total Length 106.1	Year Laid	Shape Circular		Location Details Side of Rd	
DS Manhole D20-5	Length surveyed 106.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13	

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150602	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:20	Weather Damp	
Date Cleaned 20150602			End Time 12:31	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D20-6									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
90.0 ft.	Tap Factory Made		6		0	<input checked="" type="checkbox"/>	9		
96.4 ft.	Tap Saddle		6		0	<input type="checkbox"/>	9		
103.4 ft.	Water Level				5	<input type="checkbox"/>			
106.1 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D20-5									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D20-6_D20-5	Oliver Springs	Airport Rd	PolyVinyl Chloride	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D20-6	106.1		Circular	Side of Rd	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D20-5	106.1		8	8	13



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D20-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 90.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 96.4 ft. Grade: 0
Condition: Tap Saddle
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D20-6_D20-5	Oliver Springs	Airport Rd	PolyVinyl Chloride	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D20-6	106.1		Circular	Side of Rd	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D20-5	106.1		8	8	13



Distance: 103.4 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 106.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D20-5



Pipe Segment Refere... D20-6_D20-5	City Oliver Springs	Street Airport Rd	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH D20-6	Total Length 106.1	Year Laid	Shape Circular		Location Details Side of Rd	
DS Manhole D20-5	Length surveyed 106.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150602		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:20		Weather Damp	
Date Cleaned 20150602			End Time 12:31		Additional Info	

Page #: 4