

Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
D21-4_D21-4A		Oliver Springs		Duncan DR	Concrete Pipe (non		Light High	Sanitary	
Upstream MH		Total Length		Year Laid	Shape		Location	Details	
D21-4		214.6			Circ	cular			
DS Manhole		Length surveyed		Year Renewed	Height	Width	Pipe Joint		
D21	D21-4A		4.6		6	6	4		
SPR	N/A	MPR	N/A	PO Number		PO Number Custon			
0001	-			4397-03 Work Order			GRW		
SPRI	N/A	MPRI	N/A			Purpose			
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Su		urvey	
O	PR .	Surve	yed By	Direction	Date		ate Media label		
N	/A	Barry_Rogers		Downstream	20150625				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N/A		U-1012-16405		Jetting	07:56		Dry		
		Date C	leaned	End Time		Additional Info			
		2015	0625	08:25					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Oneda
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	D21-4				-				
0.0 ft.	Water Level				5				
45.3 ft.	Tap Factory Made		6		0		3		
48.5 ft.	Tap Factory Made		6		0		9		
101.9 ft.	Tap Factory Made		6		0		3		
115.6 ft.	Tap Factory Made		6		0		9		
200.6 ft.	Tap Factory Made		6		0		9		
209.5 ft.	Water Level				5				
214.6 ft.	Access Point Manhole				0				
Remarks:	D21-4A			•					•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D21-4_D21-4A	Oliver Springs	Duncan DR	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		hape Location	
D21-4	214.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D21-4A	214.6		6	6	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: D21-4



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 45.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 48.5 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D21-4_D21-4A	Oliver Springs	Duncan DR	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
D21-4	214.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D21-4A	214.6		6	6	4	



Distance: 101.9 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A



Distance: 115.6 ft. Grade: (

Condition: Tap Factory Made

Remarks: N/A



Distance: 200.6 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 209.5 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D21-4_D21-4A	Oliver Springs	Duncan DR	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		e Location	
D21-4	214.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D21-4A	214.6		6	6	4	,



Distance: 214.6 ft. Grade: 0

Condition: Access Point Manhole

Remarks: D21-4A



PACP Conditions

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
D21-4_D21-4A		Oliver Springs		Duncan DR	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH		Total I	_ength	Year Laid	Sh	Shape		Details	
D21-4		214.6			Circ	ular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint			
D21	-4A	214.6			6	6	4		
SPR	N/A	MPR	N/A	PO Number			Customer		
SPRI	N/A	MPRI	N/A	4397-03		Pre-I			
SFRI	IN/A	IVIFKI	IN/A	Work Order					
QSR	N/A	QMR	N/A	4397-02				urvey	
OF	PR	Survey	ed By	Direction	Da	ate Media label		alabel	
N/	/A	Barry_	Rogers	Downstream	2015	20150625			
OP	OPRI		e Number	Pre-Cleaning	Ti	Time			
N/A		U-1012-16405		Jetting	07	07:56			
		Date C	leaned	End Time		Additional Info			
		2015	0625	08	:25				

	Stru	ctural Rat	ings	0	& M Ratin	gs	Com	nbined Ra	ings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	0	0	2	0	0
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY	Pipe Rating Structural Index		0	Pipe Rating O&M Index		0	Overall Pipe Rating Overall Index		0
		ick Rating	0000	1	ick Rating	0000	1	ick Rating	0000