



Defect Listing

Pipe Segment Refere... D3-3_D3-2	City Oliver Springs	Street Highway 62	Material Concrete Pipe (non-...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH D3-3	Total Length 228.7	Year Laid	Shape Circular	Location Details	
DS Manhole D3-2	Length surveyed 228.7	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Upstream	Date 20150708	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:31	Weather Damp	
Date Cleaned 20150708			End Time 08:44	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D3-2									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
228.7 ft.	Water Level				10	<input type="checkbox"/>			
228.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D3-3									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D3-3_D3-2	Oliver Springs	Highway 62	Concrete Pipe (non-...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D3-3	228.7		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D3-2	228.7		8	8	4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D3-2



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 228.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 228.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D3-3



Pipe Segment Refere... D3-3_D3-2	City Oliver Springs	Street Highway 62	Material Concrete Pipe (non-...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH D3-3	Total Length 228.7	Year Laid	Shape Circular		Location Details	
DS Manhole D3-2	Length surveyed 228.7	Year Renewed	Height 8	Width 8	Pipe Joint... 4	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Upstream	Date 20150708		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:31		Weather Damp	
Date Cleaned 20150708			End Time 08:44		Additional Info	

Page #: 3