



## Defect Listing

Pipe Segment Refere... <b>D6-1_D-15</b>	City <b>Oliver Springs</b>	Street <b>Midway DR</b>	Material <b>Fibreglass Reinf...</b>	Location C... <b>Yard</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>D6-1</b>	Total Length <b>52.4</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>D-15</b>	Length surveyed <b>52.4</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>				
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150707</b>	Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>07:27</b>	Weather <b>Dry</b>	
Date Cleaned <b>20150707</b>			End Time <b>07:34</b>	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D6-1									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
50.6 ft.	Water Level				10	<input type="checkbox"/>			
52.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D-15									



## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D6-1_D-15	Oliver Springs	Midway DR	Fibreglass Reinforc...	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D6-1	52.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-15	52.4		8	8	N/A



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D6-1



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 50.6 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 52.4 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D-15



Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D6-1_D-15	Oliver Springs	Midway DR	Fibreglass Reinforc...	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D6-1	52.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-15	52.4		8	8	N/A
SPR	N/A	MPR	N/A	Customer	
SPRI	N/A	MPRI	N/A	GRW	
QSR	N/A	QMR	N/A	Purpose	
OPR	Surveyed By	Direction	Date	Media label	
N/A	Barry_Rogers	Downstream	20150707		
OPRI	Certificate Number	Pre-Cleaning	Time	Weather	
N/A	U-1012-16405	Jetting	07:27	Dry	
Date Cleaned			End Time	Additional Info	
20150707			07:34		

Page #: 3