



Defect Listing

Pipe Segment Refere... D8-4_D8-3	City Oliver Springs	Street Highway #61 &# 62	Material Concrete Pipe (non-...	Location C... Main Highw...	Sewer Use Sanitary
Upstream MH D8-4	Total Length 289.1	Year Laid	Shape Circular	Location Details	
DS Manhole D8-3	Length surveyed 289.1	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150706	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:01	Weather Dry	
Date Cleaned 20150706			End Time 07:16	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D8-4									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
37.3 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
145.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
286.8 ft.	Water Level				5	<input type="checkbox"/>			
289.1 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D8-3									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D8-4_D8-3	Oliver Springs	Highway #61 &# 62	Concrete Pipe (non-...	Main Highw...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D8-4	289.1		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D8-3	289.1		8	8	4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D8-4



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 37.3 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 145.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D8-4_D8-3	Oliver Springs	Highway #61 &# 62	Concrete Pipe (non-...	Main Highw...	Sanitary
Upstream MH D8-4	Total Length 289.1	Year Laid	Shape Circular	Location Details	
DS Manhole D8-3	Length surveyed 289.1	Year Renewed	Height 8	Width 8	Pipe Joint... 4



Distance: 286.8 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 289.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D8-3



PACP Conditions

Pipe Segment Refere...	City	Street	Material		Location C...	Sewer Use
D8-4_D8-3	Oliver Springs	Highway #61 &# 62	Concrete Pipe (non-...		Main Highw...	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
D8-4	289.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...	
D8-3	289.1		8	8	4	

SPR	N/A	MPR	N/A	PO Number		Customer	
SPRI	N/A	MPRI	N/A	4397-03		GRW	
QSR	N/A	QMR	N/A	Work Order		Purpose	
				4397-02		Pre-Rehabilitation Survey	
OPR		Surveyed By		Direction	Date	Media label	
N/A		Barry_Rogers		Downstream	20150706		
OPRI		Certificate Number		Pre-Cleaning	Time	Weather	
N/A		U-1012-16405		Jetting	07:01	Dry	
Date Cleaned				End Time		Additional Info	
20150706				07:16			

[illegible]