ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
E-11_E-10		Oliver Springs		NUII	Concrete Pipe (non		Easement/R	Sanitary	
Upstream MH		Total Length		Year Laid	Sha	ape	Location Details		
E-11		36	9.7		Circ	ular	Cow Pasture		
DS Manhole		Length surveyed		Year Renewed	Height	Width	Pipe Joint		
E-	E-10		9.7		8	8	4		
SPR	N/A	MPR	10	PO Number		Customer			
CDDI	NI/A	MDDI		4397-03			GRW		
SPRI	N/A	MPRI	2.5	Work Order		Purpose			
QSR	N/A	QMR	4123	4397-02	4397-02		Pre-Rehabilitation Surv		
OF	PR	Surve	yed By	Direction	Date		Media label		
1	0	Barry_Rogers		Downstream	20150610				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2.5		U-1012-16405		Jetting	08:42		Dry		
		Date C	Cleaned	End Time		Additional Info			
		2015	0610	09:22					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		0
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	E-11				-				
0.0 ft.	Water Level				10				
192.9 ft.	Tap Break-In		6		0		2		
245.3 ft.	Water Level Sag				15				2
315.6 ft.	Water Level Sag				20				2
356.5 ft.	Water Level Sag				20				2
368.5 ft.	Camera Underwater				0				4
369.7 ft.	Water Level				20				
369.7 ft.	Access Point Manhole				0				
Remarks:	E-10			•	•		'		•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E-11_E-10	Oliver Springs	NUII	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
E-11	369.7		Circular		Cow P	asture
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E-10	369.7		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: E-11



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 192.9 ft. Grade: 0

Condition: Tap Break-In

Remarks: N/A



Distance: 245.3 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E-11_E-10	Oliver Springs	NUII	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
E-11	369.7		Circular		Cow P	asture
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E-10	369.7		8	8	4	



Distance: 315.6 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 356.5 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 368.5 ft. Grade: 4

Condition: Camera Underwater

Remarks: N/A



Distance: 369.7 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E-11_E-10	Oliver Springs	NUII	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
E-11	369.7		Circular		Cow P	asture
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E-10	369.7		8	8	4	



Distance: 369.7 ft. Grade: 0

Condition: Access Point Manhole

Remarks: E-10



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
E-11_E-10		Oliver Springs		NUII	Concrete F	Concrete Pipe (non		Sanitary
Upstream MH		Total Length		Year Laid	Sh	ape	Location Details	
E-	11	36	9.7		Circ	Circular Cov		asture
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	idth Pipe Joint	
E-	E-10		9.7		8	8	4	
SPR	N/A	MPR	10	PO Number	PO Number		Customer	
SPRI	N/A	MPRI	2.5	4397-03			GRW	
01 IXI	11//	IVII IXI	2.5	Work Order				
QSR	N/A	QMR	4123	4397-02		Pre-	Pre-Rehabilitation Survey	
OF	PR .	Surve	yed By	Direction Da		ate Media label		label
1	0	Barry_Rogers		Downstream	20150610			
OF	OPRI		e Number	Pre-Cleaning	Ti	Time		
2.5		U-1012-16405		Jetting	08	08:42		
		Date C	Cleaned	End Time		Additional Info		
		2015	0610	09	:22			

	Stru	ctural Rat	ings	0	& M Ratin	gs	Con	bined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		_	_		_	_		_	_
	1	0	0	1	0	0	1	0	0
	2	0	0	2	3	6	2	3	6
	3	0	0	3	0	0	3	0	0
	4	0	0	4	1	4	4	1	4
	5	0	0	5	0	0	5	0	0
Continuous Defects	-								
Code ID Length	-								
	Subtotals	0		Subtotals	4		Subtotals	4	
OUR A DV		ipe Rating	0		pe Rating	10		pe Rating	10
SUMMARY		ural Index	0		&M Index	2.5		erall Index	2.5
	1	ick Rating	0000	1	ick Rating	4123	1	ick Rating	4123