



Defect Listing

Pipe Segment Refere... E-13_E-12	City Oliver Springs	Street Cedar Ln	Material PolyVinyl Chloride	Location C... Yard	Sewer Use Sanitary
Upstream MH E-13	Total Length 7.3	Year Laid	Shape Circular	Location Details Front Yard	
DS Manhole E-12	Length surveyed 7.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR 2	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI 2	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 2100	QMR N/A				
OPR 2	Surveyed By Barry Rogers	Direction Upstream	Date 20150608	Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 11:52	Weather Dry	
Date Cleaned 20150608			End Time 11:56	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E-12									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
6.0 ft.	Water Level				15	<input type="checkbox"/>			
7.3 ft.	Joint Offset Large				0	<input type="checkbox"/>			2
Remarks: point repair defect									
7.3 ft.	Survey Abandoned				0	<input type="checkbox"/>			
Remarks: survey complete									




Image Report 4/Page


Pipe Segment Refere... E-13_E-12	City Oliver Springs	Street Cedar Ln	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E-13	Total Length 7.3	Year Laid	Shape Circular		Location Details Front Yard	
DS Manhole E-12	Length surveyed 7.3	Year Renewed	Height 8	Width 8	Pipe Joint...	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E-12



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 6.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A




Distance: 7.3 ft. Grade: 2
Condition: Joint Offset Large
Remarks: point repair defect



Image Report 4/Page

Pipe Segment Refere... E-13_E-12	City Oliver Springs	Street Cedar Ln	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E-13	Total Length 7.3	Year Laid	Shape Circular		Location Details Front Yard	
DS Manhole E-12	Length surveyed 7.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 7.3 ft. Grade: 0
Condition: Survey Abandoned
Remarks: survey complete



Pipe Segment Refere... E-13_E-12	City Oliver Springs	Street Cedar Ln	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E-13	Total Length 7.3	Year Laid	Shape Circular		Location Details Front Yard	
DS Manhole E-12	Length surveyed 7.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR 2	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI 2	MPRI N/A	Work Order 4397-02		Purpose		
QSR 2100	QMR N/A			Pre-Rehabilitation Survey		
OPR 2	Surveyed By Barry_Rogers	Direction Upstream	Date 20150608		Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 11:52		Weather Dry	
Date Cleaned 20150608			End Time 11:56		Additional Info	

Page #: 4