



Defect Listing

Pipe Segment Refere... E-17_E-16	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride	Location C... Yard	Sewer Use Sanitary
Upstream MH E-17	Total Length 45.9	Year Laid	Shape Circular	Location Details Crosses Sleepy Holl...	
DS Manhole E-16	Length surveyed 45.9	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150604	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 13:04	Weather Dry	
Date Cleaned 20150604			End Time 13:11	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E-17									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
45.0 ft.	Water Level				5	<input type="checkbox"/>			
45.9 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E-16									



Image Report 4/Page


Pipe Segment Refere... E-17_E-16	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E-17	Total Length 45.9	Year Laid	Shape Circular		Location Details Crosses Sleepy Holl...	
DS Manhole E-16	Length surveyed 45.9	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E-17



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 45.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 45.9 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E-16



PACP Conditions

Pipe Segment Refere... E-17_E-16	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride	Location C... Yard	Sewer Use Sanitary
Upstream MH E-17	Total Length 45.9	Year Laid	Shape Circular	Location Details Crosses Sleepy Holl...	
DS Manhole E-16	Length surveyed 45.9	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150604
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 13:04
	Date Cleaned 20150604	End Time 13:11	Weather Dry
		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									