



Defect Listing

Pipe Segment Refere... E10-4 E10-1	City Oliver Springs	Street Sturbridge Dr	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E10-4	Total Length 93.3	Year Laid	Shape Circular	Location Details New Subdivision	
DS Manhole E10-1	Length surveyed 93.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150617	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:22	Weather Very Dry	
Date Cleaned 20150617			End Time 10:30	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	☐			
Remarks: E10-4									
0.0 ft.	Water Level				0	☐			
36.4 ft.	Tap Factory Made		6		0	☒	9		
57.6 ft.	Tap Factory Made		6		0	☐	9		
92.9 ft.	Water Level				0	☐			
93.3 ft.	Access Point Manhole				0	☐			
Remarks: E10-1									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material		Location C...	Sewer Use
E10-4 E10-1	Oliver Springs	Sturbridge Dr	PolyVinyl Chloride		Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E10-4	93.3		Circular		New Subdivision	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...	
E10-1	93.3		8	8	13	



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E10-4



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 36.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 57.6 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page


Pipe Segment Refere... E10-4 E10-1	City Oliver Springs	Street Sturbridge Dr	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E10-4	Total Length 93.3	Year Laid	Shape Circular		Location Details New Subdivision	
DS Manhole E10-1	Length surveyed 93.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 92.9 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 93.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E10-1



Pipe Segment Refere... E10-4_E10-1	City Oliver Springs	Street Sturbridge Dr	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E10-4	Total Length 93.3	Year Laid	Shape Circular		Location Details New Subdivision	
DS Manhole E10-1	Length surveyed 93.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A	Pre-Rehabilitation Survey				
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150617		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:22		Weather Very Dry	
Date Cleaned 20150617			End Time 10:30		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									