



Defect Listing

Pipe Segment Refere... E10-5_E10-4	City Oliver Springs	Street Sturbridge dr	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E10-5	Total Length 68.1	Year Laid	Shape Circular	Location Details New Subdivision	
DS Manhole E10-4	Length surveyed 68.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150617	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:09	Weather Very Dry	
Date Cleaned 20150617			End Time 10:15	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	☐			
Remarks: E10-5									
0.0 ft.	Water Level				5	☐			
66.9 ft.	Water Level				5	☐			
68.1 ft.	Access Point Manhole				0	☐			
Remarks: E10-4									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E10-5_E10-4	Oliver Springs	Sturbridge dr	PolyVinyl Chloride	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E10-5	68.1		Circular	New Subdivision	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E10-4	68.1		8	8	13



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E10-5




Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 66.9 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 68.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E10-4



PACP Conditions

Pipe Segment Refere...	City	Street	Material		Location C...	Sewer Use
E10-5_E10-4	Oliver Springs	Sturbridge dr	PolyVinyl Chloride		Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E10-5	68.1		Circular		New Subdivision	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...	
E10-4	68.1		8	8	13	

SPR	N/A	MPR	N/A	PO Number		Customer	
SPRI	N/A	MPRI	N/A	4397-03		GRW	
QSR	N/A	QMR	N/A	Work Order		Purpose	
				4397-02		Pre-Rehabilitation Survey	
OPR		Surveyed By		Direction	Date	Media label	
N/A		Barry_Rogers		Downstream	20150617		
OPRI		Certificate Number		Pre-Cleaning	Time	Weather	
N/A		U-1012-16405		Jetting	10:09	Very Dry	
Date Cleaned				End Time		Additional Info	
20150617				10:15			

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									