



Defect Listing

Pipe Segment Refere... E10-6_E10-2	City Oliver Springs	Street Sturbridge Dr	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E10-6	Total Length 91.8	Year Laid	Shape Circular	Location Details New Subdivision	
DS Manhole E10-2	Length surveyed 91.8	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Upstream	Date 20150617	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning No Pre-Cleaning	Time 11:02	Weather Very Dry	
Date Cleaned			End Time 11:09	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	☐			
Remarks: E10-6									
0.0 ft.	Water Level				0	☐			
86.5 ft.	Tap Factory Made		6		0	☐	3		
91.8 ft.	Water Level				5	☐			
91.8 ft.	Access Point Manhole				0	☐			
Remarks: E10-2									




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E10-6_E10-2	Oliver Springs	Sturbridge Dr	PolyVinyl Chloride	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E10-6	91.8		Circular	New Subdivision	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E10-2	91.8		8	8	13



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E10-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 86.5 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 91.8 ft. Grade: 0
Condition: Water Level
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere... E10-6_E10-2	City Oliver Springs	Street Sturbridge Dr	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E10-6	Total Length 91.8	Year Laid	Shape Circular		Location Details New Subdivision	
DS Manhole E10-2	Length surveyed 91.8	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 91.8 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E10-2



Pipe Segment Refere... E10-6_E10-2	City Oliver Springs	Street Sturbridge Dr	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E10-6	Total Length 91.8	Year Laid	Shape Circular		Location Details New Subdivision	
DS Manhole E10-2	Length surveyed 91.8	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A					
OPR N/A	Surveyed By Barry_Rogers	Direction Upstream	Date 20150617		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning No Pre-Cleaning	Time 11:02		Weather Very Dry	
Date Cleaned			End Time 11:09		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects CodeIDLength			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Subtotals			0		Subtotals	0		Subtotals	0		
SUMMARY			Pipe Rating	0	Pipe Rating	0	Overall Pipe Rating	0			
			Structural Index	0	O&M Index	0	Overall Index	0			
			Str. Quick Rating	0000	O&M Quick Rating	0000	Ovrl. Quick Rating	0000			