



Defect Listing

Pipe Segment Refere... E12-4_E13-6	City Oliver Springs	Street Oak Circle	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH E12-4	Total Length 220.6	Year Laid	Shape Circular	Location Details Street	
DS Manhole E13-6	Length surveyed 220.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150610	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:53	Weather Dry	
Date Cleaned 20150610			End Time 15:04	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E12-4									
0.0 ft.	Water Level				0	<input type="checkbox"/>			
19.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
61.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
220.6 ft.	Water Level				0	<input type="checkbox"/>			
220.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E13-6									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E12-4_E13-6	Oliver Springs	Oak Circle	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH E12-4	Total Length 220.6	Year Laid	Shape Circular	Location Details Street	
DS Manhole E13-6	Length surveyed 220.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E12-4



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 19.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 61.7 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... E12-4_E13-6	City Oliver Springs	Street Oak Circle	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH E12-4	Total Length 220.6	Year Laid	Shape Circular		Location Details Street	
DS Manhole E13-6	Length surveyed 220.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4	



Distance: 220.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 220.6 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E13-6



PACP Conditions

Pipe Segment Refere... E12-4_E13-6	City Oliver Springs	Street Oak Circle	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH E12-4	Total Length 220.6	Year Laid	Shape Circular		Location Details Street	
DS Manhole E13-6	Length surveyed 220.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey		
QSR N/A	QMR N/A					
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150610		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:53		Weather Dry	
Date Cleaned 20150610			End Time 15:04		Additional Info	

[illegible]