

## **Defect Listing**

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
E13-6_	_E13-5	Oliver	Springs	Valley Dr	/alley Dr Concrete Pipe (non		Light High	Sanitary	
Upstream MH		Total Length		Year Laid	Sh	Shape		Details	
E1:	3-6	32	6.5		Circular		Str	eet	
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	ht Width Pipe Joint			
E1:	3-5	326.5			8	8	4		
SPR	N/A	MPR	N/A	PO Number 4397-03 Work Order		Customer			
0001		MDDI				GRW			
SPRI	N/A	MPRI	N/A			Purpose			
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Survey		urvey	
OF	PR	Surve	yed By	Direction	Di	Date Media la		alabel	
N/	N/A		Rogers	Downstream	20150609				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N/	N/A		2-16405	Jetting	09:35		Saturated		
	Date Cleaned			Er		End Time A		nal Info	
	20150609				09:51				

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	E13-6								
0.0 ft.	Water Level				10				
159.5 ft.	Tap Factory Made		6		0		9		
199.0 ft.	Tap Factory Made		6		0		3		
322.7 ft.	Tap Factory Made		6		0		9		
325.6 ft.	Water Level				5				
326.5 ft.	Access Point Manhole				0				
Remarks:	E13-5								





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E13-6_E13-5	Oliver Springs	Valley Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E13-6	326.5		Circular		Str	eet
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
DO MAINTON	Longin Surveyed	Tour Nonewoo	ricigiit	vvidin	i ipo domit	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: E13-6



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 159.5 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 199.0 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E13-6_E13-5	Oliver Springs	Valley Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E13-6	326.5		Circular		Str	eet
		l .				
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	



Distance: 322.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 325.6 ft. Grade: 0

Condition: Water Level

Remarks: N/A



**Distance**: 326.5 ft. **Grade**: 0

Access Point Manhole

Remarks: E13-5

Condition:



## **PACP Conditions**

Pipe Segment Refere		С	ity	Street	Mat	erial	Location C	Sewer Use	
E13-6	_E13-5	Oliver	Springs	Valley Dr	Concrete F	Concrete Pipe (non		Sanitary	
Upstre	am MH	Total I	Length	Year Laid	Sha	Shape Loca		Location Details	
E1	3-6	32	6.5		Circ	Circular S		Street	
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint			
E1	3-5	32	6.5		8	8 4			
SPR	N/A	MPR	N/A	PO Number	PO Number		Customer		
SPRI	N/A	MPRI	N/A	4397-03					
SPRI	IN/A	IVIFKI	IN/A	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre-F	Pre-Rehabilitation Survey		
OI	PR .	Surve	yed By	Direction	Da	Date Media label		alabel	
N.	/A	Barry_Rogers		Downstream	20150609				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
N.	/A	U-1012-16405		Jetting	09:35		Saturated		
		Date C	Cleaned		End	End Time		nal Info	
		2015	0609		09:51				

		Stru	Structural Ratings			& M Ratin	gs	Con	nbined Ra	tings
Normal [	Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		4			4			4		_
		2	0	0	2	0	0	2	0	0
			0	0		0	0		0	0
		3	0	0	3	0	0	3	0	0
		4	0	0	4	0	0	4	0	0
		5	0	0	5	0	0	5	0	0
Continuou	s Defects									
Code II	D Length									
		Subtotals	0		Subtotals	0		Subtotals	0	
SUMI	MARY	   Pi	pe Rating	0	   Pi	pe Rating	0	Overall P	pe Rating	0
551111		Struct	ural Index	0	0	&M Index	0	Ove	erall Index	0
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Qu	ick Rating	0000