ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
E15-2_E15-2A		Oliver Springs		Sleepy Hollow	PolyViny	PolyVinyl Chloride		Sanitary	
Upstrea	am MH	Total	Length	Year Laid	Sha	ape	Location Details		
E15	5-2	34	7.4		Circ	ular	Houses		
DS Ma	anhole	Length	surveyed	Year Renewed	Height	Width	Pipe Joint		
E15	-2A	347.4			8	8	13		
SPR	N/A	MPR	44	PO Number 4397-03			Customer		
2001	-					GRW			
SPRI	N/A	MPRI	2	Work Order		Purpose			
QSR	N/A	QMR	2C00	4397-02		Pre	Pre-Rehabilitation Survey		
OF	PR	Surveyed By		Direction	Da	Date Media la		alabel	
4	4	Barry_Rogers		Downstream	20150605				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2	2	U-1012-16405		Jetting	09	09:22			
	Date Cleaned						Additional Info		
l	20150605						Manholes are Not La		

Distance	Con distan	Comt Diet	Values			laint	Clock Position		Oneste
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	E15-2	•							
0.0 ft.	Water Level				5				
24.7 ft.	Tap Factory Made		6		0	4	9		
112.8 ft.	Tap Factory Made		6		0	4	9		
213.1 ft.	Tap Factory Made		6		0	4	9		
256.2 ft.	Water Level Sag	S01			20				2
285.1 ft.	Water Level				10				
314.2 ft.	Tap Break-In Intruding		6	1	0	4	9		2
330.9 ft.	Water Level Sag	S02			20				2
347.2 ft.	Water Level				10				
347.4 ft.	Access Point Manhole				0				
Remarks:	E15-2A	•							
347.4 ft.	Water Level Sag	F02			20				2
347.4 ft.	Water Level Sag	F01			20				2





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E15-2_E15-2A	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E15-2	347.4		Circular		Behind	Houses
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E15-2A	347.4		8	8	13	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: E15-2



Distance: 0.0 ft. Grade: (

Condition: Water Level

Remarks: N/A



Distance: 24.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 112.8 ft. Grade: 0

Condition: Tap Factory Made





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E15-2_E15-2A	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E15-2	347.4		Circular		Behind	Houses
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E15-2A	347.4		8	8	13	



Distance: 213.1 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 256,2 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 285.1 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 314.2 ft. Grade: 2

Condition: Tap Break-In Intruding





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E15-2_E15-2A	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E15-2	347.4		Circular		Behind	Houses
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E15-2A	347.4		8	8	13	



Distance: 330.9 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 347.2 ft. Grade: (

Condition: Water Level

Remarks: N/A



Distance: 347.4 ft. Grade: 0

Condition: Access Point Manhole

Remarks: E15-2A



Distance: 347.4 ft. Grade: 2

Condition: Water Level Sag

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

	Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	E15-2_E15-2A	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride		Easement/R	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location Details	
	E15-2	347.4		Circular		Behind Houses	
	DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
l	E15-2A	347.4		8	8	13	



Distance: 347.4 ft. Grade: 2

Condition: Water Level Sag



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
E15-2_E15-2A Olive		Springs	Sleepy Hollow	PolyViny	PolyVinyl Chloride		Sanitary	
Upstre	Upstream MH Total Length		Length	Year Laid	Sha	ape	Location	Details
E1	5-2	34	7.4		Circ	Circular		Houses
DS Ma	anhole	Length :	surveyed	Year Renewed	Height	Width	th Pipe Joint	
E15	E15-2A		7.4		8	8	13	
SPR	N/A	MPR	44	PO Number			Customer	
SPRI	N/A	MPRI	2	4397-03			GRW	
0110	17/4	IVII IXI		Work Order				
QSR	N/A	QMR	2C00	4397-02		Pre-Rehabilitation Survey		urvey
OI	PR .	Surveyed By		Direction	Da	Date Media label		label
4	4	Barry_	Rogers	Downstream	2015	20150605		
OF	PRI	Certificat	te Number	Pre-Cleaning	Tir	me	Weather	
:	2		2-16405	Jetting	09	:22	Dry	
	Date Cleaned					End Time		nal Info
	20150605					09:49 Manholes a		re Not La

			Structural Ratings			О	& M Ratin	gs	Con	nbined Ra	tings
Norm	al Def	ects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
							_	_	_	_	
			1	0	0	1	0	0	1	0	0
			2	0	0	2	1	2	2	1	2
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code											
Code	ID	Length									
MWLS	F01	91.2	0	0	0	2	18	36	2	18	36
MWLS	F02	16.5	0	0	0	2	3	6	2	3	6
			Subtotals	0		Subtotals	22		Subtotals	22	
SUMMARY		Pi	pe Rating	0	Pi	pe Rating	44	Overall Pi	pe Rating	44	
			ural Index	0		&M Index	2.0		erall Index	2.0	
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2C00	Ovrl. Quick Rating		2C00	