



Defect Listing

Pipe Segment Refere... E15-4_E15-3	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E15-4	Total Length 34.7	Year Laid	Shape Circular	Location Details Side of Rd	
DS Manhole E15-3	Length surveyed 34.7	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Upstream	Date 20150605	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:03	Weather Dry	
Date Cleaned 20150604			End Time 07:26	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E15-3									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
33.5 ft.	Water Level				5	<input type="checkbox"/>			
34.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E15-4									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E15-4_E15-3	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E15-4	34.7		Circular	Side of Rd	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E15-3	34.7		8	8	13



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E15-3




Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 33.5 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 34.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E15-4



PACP Conditions

Pipe Segment Refere... E15-4_E15-3	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E15-4	Total Length 34.7	Year Laid	Shape Circular		Location Details Side of Rd	
DS Manhole E15-3	Length surveyed 34.7	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey		
QSR N/A	QMR N/A					
OPR N/A	Surveyed By Barry_Rogers	Direction Upstream	Date 20150605		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:03		Weather Dry	
Date Cleaned 20150604			End Time 07:26		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									