



Defect Listing

Pipe Segment Refere... E15-6_E15-5	City Oliver Springs	Street Red Bud Ln	Material PolyVinyl Chloride	Location C... Yard	Sewer Use Sanitary
Upstream MH E15-6	Total Length 140.7	Year Laid	Shape Circular	Location Details Side of rd in front...	
DS Manhole E15-5	Length surveyed 140.7	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150604	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:31	Weather Dry	
Date Cleaned 20150604			End Time 07:45	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E15-6									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
140.2 ft.	Water Level				5	<input type="checkbox"/>			
140.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E15-5									




Image Report 4/Page

Pipe Segment Refere... E15-6_E15-5	City Oliver Springs	Street Red Bud Ln	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E15-6	Total Length 140.7	Year Laid	Shape Circular		Location Details Side of rd in front...	
DS Manhole E15-5	Length surveyed 140.7	Year Renewed	Height 8	Width 8	Pipe Joint...	



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E15-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 140.2 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 140.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E15-5



Pipe Segment Refere... E15-6_E15-5	City Oliver Springs	Street Red Bud Ln	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E15-6	Total Length 140.7	Year Laid	Shape Circular		Location Details Side of rd in front...	
DS Manhole E15-5	Length surveyed 140.7	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150604		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:31		Weather Dry	
Date Cleaned 20150604			End Time 07:45		Additional Info	

Page #: 3