



Defect Listing

Pipe Segment Refere... E16-1 E15-3	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E16-1	Total Length 203.1	Year Laid	Shape Circular	Location Details Side of Rd	
DS Manhole E15-3	Length surveyed 203.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150604	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:41	Weather Dry	
Date Cleaned 20150604			End Time 15:02	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	☐			
Remarks: E16-1									
0.0 ft.	Water Level				5	☐			
60.4 ft.	Tap Factory Made		6		0	☒	3		
123.5 ft.	Tap Factory Made		6		0	☒	3		
202.3 ft.	Water Level				5	☐			
203.1 ft.	Access Point Manhole				0	☐			
Remarks: E15-3									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E16-1 E15-3	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E16-1	203.1		Circular	Side of Rd	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E15-3	203.1		8	8	13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E16-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 60.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 123.5 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Image Report 4/Page


Pipe Segment Refere... E16-1 E15-3	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E16-1	Total Length 203.1	Year Laid	Shape Circular		Location Details Side of Rd	
DS Manhole E15-3	Length surveyed 203.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 202.3 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 203.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E15-3



Pipe Segment Refere... E16-1_E15-3	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH E16-1	Total Length 203.1	Year Laid	Shape Circular		Location Details Side of Rd	
DS Manhole E15-3	Length surveyed 203.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150604		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:41		Weather Dry	
Date Cleaned 20150604		End Time 15:02		Additional Info		

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects CodeIDLength			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Subtotals			0		Subtotals	0		Subtotals	0		
SUMMARY			Pipe Rating	0	Pipe Rating	0	Overall Pipe Rating	0			
			Structural Index	0	O&M Index	0	Overall Index	0			
			Str. Quick Rating	0000	O&M Quick Rating	0000	Ovrl. Quick Rating	0000			