

Defect Listing

Pipe Segme	nt Refere	С	ity	Street	Mat	erial	Location C	Sewer Use	
E17-1_	E15-4	Oliver	Springs	Sleepy Hollow rd	PolyViny	PolyVinyl Chloride		Sanitary	
Upstrea	am MH	Total I	_ength	Year Laid	Sh	ape	Locatio	tion Details	
E17	7-1	31	1.6		Circ	cular	Side	of rd	
DS Ma	inhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
E1:	5-4	31	1.6		8	8	13		
SPR	N/A	MPR	13	PO Number					
ODDI	N1/A	MDDI		4397-03			GRW		
SPRI	N/A	MPRI	2.6	Work Order			Purpose		
QSR	N/A	QMR	4222	4397-02		Pre-	Pre-Rehabilitation Surve		
OF	PR	Surve	yed By	Direction	D	ate	Medi	a label	
1:	3	Barry_	Rogers	Downstream	2015	0604			
OP	RI	Certificat	e Number	Pre-Cleaning	Ti	me	Weather		
2.	6	U-1012	2-16405	Jetting	13:42		Dry		
Date Cleaned			End Time A		Additio	onal Info			
20150604				14	14:09				

Dietamas	Con disting	Cant Diat		Values		laint	Clock Position		Grade
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	E17-1			•					•
0.0 ft.	Water Level				5				
50.9 ft.	Tap Factory Made		6		0	✓	9		
55.4 ft.	Tap Factory Made Capped		6		0	✓	3		
94.2 ft.	Roots Ball Lateral				55		2		4
95.2 ft.	Tap Break-In Intruding		6	1	0		2		2
99.8 ft.	Tap Factory Made		6		0	✓	10		
107.7 ft.	Tap Factory Made Capped		6		0		2		
183.5 ft.	Tap Factory Made		6		0	_	10		
190.0 ft.	Roots Fine Joint				0	_	5		1
190.0 ft.	Tap Factory Made Capped		6		0		2		
199.1 ft.	Water Level Sag				20				2
208.1 ft.	Tap Factory Made Active		6		0	_	3		
208.1 ft.	Roots Ball Joint				55	_	2		4
259.3 ft.	Tap Factory Made Active		6		0		2		
311.6 ft.	Water Level				10				
311.6 ft.	Access Point Manhole				0				
Remarks:	E15-4								






Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E17-1_E15-4	Oliver Springs	Sleepy Hollow rd	PolyVinyl Chloride		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
E17-1	311.6		Circ	ular	Side	of rd
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E15-4	311.6		8	8	13	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: E17-1



Distance: 0.0 ft. Grade: (

Condition: Water Level

Remarks: N/A



Distance: 50.9 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance:55.4 ft.Grade:0Condition:Tap Factory Made Capped






	Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	E17-1_E15-4	Oliver Springs	Sleepy Hollow rd	PolyVinyl Chloride		Yard	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location	Details
	E17-1	311.6		Circ	cular	Side	of rd
	DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
l	E15-4	311.6		8 8		13	



Distance: 94.2 ft. Grade: 4

Condition: Roots Ball Lateral

Remarks: N/A



Distance: 95,2 ft. Grade: 2

Condition: Tap Break-In Intruding

Remarks: N/A



Distance: 99.8 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 107.7 ft. **Grade**: 0 **Condition**: Tap Factory Made Capped





Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E17-1_E15-4	Oliver Springs	Sleepy Hollow rd	PolyVinyl Chloride		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	n Details
E17-1	311.6		Circ	cular	Side	of rd
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E15-4	311.6		8	8	13	



Distance: 183.5 ft. Grade: (

Condition: Tap Factory Made

Remarks: N/A



Distance: 190.0 ft. Grade:

Condition: Roots Fine Joint

Remarks: N/A



Distance: 190.0 ft. **Grade**: 0 **Condition**: Tap Factory Made Capped

Remarks: N/A



Distance: 199.1 ft. Grade: 2

Condition: Water Level Sag





Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E17-1_E15-4	Oliver Springs	Sleepy Hollow rd	PolyVinyl Chloride		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	n Details
E17-1	311.6		Circ	cular	Side	of rd
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
E15-4	311.6		8	8	13	



Distance: 208.1 ft. Grade: 0

Condition: Tap Factory Made Active

Remarks: N/A



Distance: 208.1 ft. Grade: 4

Condition: Roots Ball Joint

Remarks: N/A



Distance: 259.3 ft. Grade: 0
Condition: Tap Factory Made Active

Remarks: N/A



Distance: 311.6 ft. Grade: 0

Condition: Water Level

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E17-1_E15-4	Oliver Springs	Sleepy Hollow rd	PolyVinyl Chloride		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
E17-1	311.6		Circ	ular	Side	of rd
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
E15-4	311.6		8	8	13	ر ا



Distance: 311.6 ft. Grade: 0

Condition: Access Point Manhole

Remarks: E15-4



PACP Conditions

Pipe Segme	ent Refere	С	ity	Street	Ma	terial	Location C	Sewer Use
E17-1	_E15-4	Oliver	Springs	Sleepy Hollow rd	PolyViny	PolyVinyl Chloride		Sanitary
Upstre	am MH	Total Length		Year Laid Shape				n Details
E1	7-1	31	1.6		Circ	cular	Side	of rd
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint	
E1:	5-4	31	1.6		8	8	13	
SPR	N/A	MPR	13	PO Number				
SPRI	N/A	MPRI	2.6	4397-03			GRW	
SFRI	IN/A	IVIFKI	2.0	Work Order			Purpose	
QSR	N/A	QMR	4222	4397-02		Pre-	Pre-Rehabilitation Survey	
OF	PR	Surve	yed By	Direction	D	Date Media lal		a label
1	3	Barry_Rogers		Downstream	2015	20150604		
OF	PRI	Certificat	e Number	Pre-Cleaning	Ti	Time		
2	2.6 U-1012-16405		2-16405	Jetting		:42	Dry	
Date Cleaned			End	Time	Additio	nal Info		
20150604				14	:09			

		Stru	ctural Rat	ings	О	& M Ratin	gs	Con	nbined Ra	tings
Normal De	efects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		1	0	0	1	4	4	1	4	4
		2	0	0	2	2	4	2	2	1
		3	0	0	3	0	0	3		0
		4	0	0	4	2	8	4	2	8
		5	0	0	5	0	0	5	0	0
				U		U				U
Continuous	Defects									
Code ID	Length									
		Subtotals	0		Subtotals	5		Subtotals	5	
SUMMARY		Pi	ipe Rating	0	Pi	pe Rating	13	Overall P	pe Rating	13
O		Struct	ural Index	0	0	&M Index	2.6	Ove	erall Index	2.6
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	4222	Ovrl. Qu	ick Rating	4222