

## **Defect Listing**

Pipe Segment Refere		С	ity	Street	Mat	erial	Location C	Sewer Use	
E5-2	_E5-1	Oliver	Springs	Ridgeview dr	Concrete F	Concrete Pipe (non		Sanitary	
Upstre	am MH	Total I	_ength	Year Laid	Sh	Shape Location D		Details	
E5	5-2	12	0.7		Circ	ular	lar Street		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Width Pipe Joint		
E5	5-1	12	0.7		8	8	4		
SPR	N/A	MPR	4	PO Number			Customer		
				<b>4397-03</b> Work Order		GRW			
SPRI	N/A	MPRI	2			Purpose			
QSR	N/A	QMR	2200	4397-02		Pre-	Pre-Rehabilitation Survey		
Ol	PR	Surve	yed By	Direction	Da	Date Media label		label	
4	4	Barry_	Rogers	Downstream 20150612					
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2		U-1012-16405		Jetting	10:23		Dry		
		Date C	leaned	E		End Time		Additional Info	
		2015	0612		10:31				

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	E5-2	·							
0.0 ft.	Water Level				5				
12.1 ft.	Water Level Sag				20				2
78.8 ft.	Water Level Sag				15				2
118.4 ft.	Water Level				5				
120.7 ft.	Access Point Manhole				0				
Remarks:	E5-1	•		•					





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E5-2_E5-1	Oliver Springs	Ridgeview dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E5-2	120.7		Circular		Str	eet
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
20 111011010	20.1gu. 00.10)00	Tour Ronowou	1.10.9.11			



Distance: 0.0 ft. Grade: (

Condition: Access Point Manhole

Remarks: E5-2



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 12.1 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 78.8 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



## Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
E5-2_E5-1	Oliver Springs	Ridgeview dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E5-2	120.7		Circular		Str	eet
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	



Distance: 118.4 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 120.7 ft. Grade:

Condition: Access Point Manhole

Remarks: E5-1



## **PACP Conditions**

Pipe Segme	ent Refere	С	ity	Street	Mat	erial	Location C	Sewer Use	
E5-2_	_E5-1	Oliver	Springs	Ridgeview dr	Concrete F	Concrete Pipe (non		Sanitary	
Upstre	am MH	Total I	Length	Year Laid	Sh	Shape Loca		ion Details	
E5	5-2	12	0.7		Circular		Str	Street	
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
E5	5-1	12	0.7		8	8	4		
SPR	N/A	MPR	4	PO Number <b>4397-03</b>			Customer		
SPRI	N/A	MPRI	2			GRW			
SFKI	IN/A	IVIFKI		Work Order		Purpose			
QSR	N/A	QMR	2200	4397-02		Pre-Rehabilitation Survey		urvey	
OF	PR	Surve	yed By	Direction	D	ate	Media	label	
4	4 Barry_Rogers		Rogers	Downstream	2015	0612			
OF	PRI	Certificate Number		Pre-Cleaning	Ti	Time			
2	2		2-16405	Jetting	10	10:23			
		Date C	leaned		End	Time	Additional Info		
		2015	0612		10	:31			

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	bined Ra	tings
Normal	Defe	cts	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
			4	_		4			4	_	
			1	0	0	1	0	0	2	0	0
			2	0	0	2	2	4		2	4
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuo	us De	efects									
Code	ID	Length									
			Subtotals	0		Subtotals	2		Subtotals	2	
SUM	/МАБ	RY	Pi	pe Rating	0	Pi	pe Rating	4	Overall P	pe Rating	4
23.1			Struct	ural Index	0	0	&M Index	2.0	Ove	erall Index	2.0
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2200	Ovrl. Qu	ick Rating	2200