



Defect Listing

Pipe Segment Refere... E6-6_E6-5	City Oliver Springs	Street Hwy61	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-6	Total Length 49.6	Year Laid	Shape Circular	Location Details Car Wash PArking Lo...	
DS Manhole E6-5	Length surveyed 49.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR 2	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 2100				
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150616	Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:45	Weather Very Dry	
Date Cleaned 20150616			End Time 08:52	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-6									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
41.5 ft.	Water Level Sag				15	<input type="checkbox"/>			2
49.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-5									




Image Report 4/Page

Pipe Segment Refere... E6-6_E6-5	City Oliver Springs	Street Hwy61	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-6	Total Length 49.6	Year Laid	Shape Circular		Location Details Car Wash PArking Lo...	
DS Manhole E6-5	Length surveyed 49.6	Year Renewed	Height 8	Width 8	Pipe Joint...	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 41.5 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Distance: 49.6 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-5



PACP Conditions

Pipe Segment Refere... E6-6_E6-5	City Oliver Springs	Street Hwy61	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-6	Total Length 49.6	Year Laid	Shape Circular	Location Details Car Wash PARKING Lo...	
DS Manhole E6-5	Length surveyed 49.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13
SPR N/A	MPR 2	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 2100				
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150616	Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:45	Weather Very Dry	
Date Cleaned 20150616			End Time 08:52	Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	1	2	2	1	2
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									