



## Defect Listing

Pipe Segment Refere... <b>E6-6A_E6-6</b>	City <b>Oliver Springs</b>	Street <b>Parking Lot</b>	Material <b>PolyVinyl Chloride</b>	Location C... <b>Parking Lo...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>E6-6A</b>	Total Length <b>161.6</b>	Year Laid	Shape <b>Circular</b>	Location Details <b>Off HWY 62</b>	
DS Manhole <b>E6-6</b>	Length surveyed <b>161.6</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>13</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>				
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150615</b>	Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>11:03</b>	Weather <b>Very Dry</b>	
Date Cleaned <b>20150615</b>			End Time <b>11:11</b>	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-6A									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
65.3 ft.	Tap Factory Made Active		6		0	<input checked="" type="checkbox"/>	2		
159.6 ft.	Water Level				5	<input type="checkbox"/>			
161.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-6									




## Image Report 4/Page


Pipe Segment Refere... <b>E6-6A E6-6</b>	City <b>Oliver Springs</b>	Street <b>Parking Lot</b>	Material <b>PolyVinyl Chloride</b>		Location C... <b>Parking Lo...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>E6-6A</b>	Total Length <b>161.6</b>	Year Laid	Shape <b>Circular</b>		Location Details <b>Off HWY 62</b>	
DS Manhole <b>E6-6</b>	Length surveyed <b>161.6</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>13</b>	




Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: E6-6A



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 65.3 ft. Grade: 0  
Condition: Tap Factory Made Active  
Remarks: N/A



Distance: 159.6 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



## Image Report 4/Page

Pipe Segment Refere... <b>E6-6A_E6-6</b>	<b>City</b> <b>Oliver Springs</b>	<b>Street</b> <b>Parking Lot</b>	<b>Material</b> <b>PolyVinyl Chloride</b>		<b>Location C...</b> <b>Parking Lo...</b>	<b>Sewer Use</b> <b>Sanitary</b>
<b>Upstream MH</b> <b>E6-6A</b>	Total Length <b>161.6</b>	Year Laid	<b>Shape</b> <b>Circular</b>		Location Details <b>Off HWY 62</b>	
<b>DS Manhole</b> <b>E6-6</b>	<b>Length surveyed</b> <b>161.6</b>	Year Renewed	<b>Height</b> <b>8</b>	Width <b>8</b>	Pipe Joint... <b>13</b>	



Distance: 161.6 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: E6-6



Pipe Segment Refere... E6-6A_E6-6	City Oliver Springs	Street Parking Lot	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-6A	Total Length 161.6	Year Laid	Shape Circular		Location Details Off HWY 62	
DS Manhole E6-6	Length surveyed 161.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150615		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 11:03		Weather Very Dry	
Date Cleaned 20150615			End Time 11:11		Additional Info	

Page #: 4