



Defect Listing

Pipe Segment Refere... E6-8_E6-7	City Oliver Springs	Street Parking LOt	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-8	Total Length 101.7	Year Laid	Shape Circular	Location Details Off HWY 62	
DS Manhole E6-7	Length surveyed 101.7	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150615	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:01	Weather Very Dry	
Date Cleaned 20150615			End Time 10:11	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-8									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
100.0 ft.	Water Level				5	<input type="checkbox"/>			
101.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-7									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E6-8_E6-7	Oliver Springs	Parking LOt	PolyVinyl Chloride	Parking Lo...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E6-8	101.7		Circular	Off HWY 62	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E6-7	101.7		8	8	13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-8



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 100.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 101.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-7



PACP Conditions

Pipe Segment Refere...	City	Street	Material		Location C...	Sewer Use
E6-8_E6-7	Oliver Springs	Parking LOT	PolyVinyl Chloride		Parking Lo...	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E6-8	101.7		Circular		Off HWY 62	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...	
E6-7	101.7		8	8	13	

SPR	N/A	MPR	N/A	PO Number		Customer	
SPRI	N/A	MPRI	N/A	4397-03		GRW	
QSR	N/A	QMR	N/A	Work Order		Purpose	
				4397-02		Pre-Rehabilitation Survey	
OPR	N/A	Surveyed By Barry_Rogers		Direction Downstream	Date 20150615	Media label	
OPRI	N/A	Certificate Number U-1012-16405		Pre-Cleaning Jetting	Time 10:01	Weather Very Dry	
Date Cleaned 20150615					End Time 10:11	Additional Info	

[illegible]