



Defect Listing

Pipe Segment Refere... E6-9_E6-8	City Oliver Springs	Street Parking Lot	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-9	Total Length 75.6	Year Laid	Shape Circular	Location Details Church Parking LOt	
DS Manhole E6-8	Length surveyed 75.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150615	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:52	Weather Dry	
Date Cleaned 20150615			End Time 09:58	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-9									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
75.6 ft.	Water Level				5	<input type="checkbox"/>			
75.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-8									




Image Report 4/Page

Pipe Segment Refere... E6-9_E6-8	City Oliver Springs	Street Parking Lot	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-9	Total Length 75.6	Year Laid	Shape Circular		Location Details Church Parking LOT	
DS Manhole E6-8	Length surveyed 75.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-9



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 75.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 75.6 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-8



PACP Conditions

Pipe Segment Refere... E6-9_E6-8	City Oliver Springs	Street Parking Lot	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-9	Total Length 75.6	Year Laid	Shape Circular	Location Details Church Parking LOT	
DS Manhole E6-8	Length surveyed 75.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream		Date 20150615	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 09:52		Weather Dry	
Date Cleaned 20150615			End Time 09:58		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	