



Defect Listing

Pipe Segment Refere... E6-9A_E6-9	City Oliver Springs	Street Easement	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-9A	Total Length 204.6	Year Laid	Shape Circular	Location Details Church Parking Lot	
DS Manhole E6-9	Length surveyed 204.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150615	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:26	Weather Very Dry	
Date Cleaned 20150615			End Time 09:36	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-9A									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
201.7 ft.	Water Level				5	<input type="checkbox"/>			
204.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-9									




Image Report 4/Page

Pipe Segment Refere... E6-9A_E6-9	City Oliver Springs	Street Easement	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E6-9A	Total Length 204.6	Year Laid	Shape Circular		Location Details Church Parking Lot	
DS Manhole E6-9	Length surveyed 204.6	Year Renewed	Height 8	Width 8	Pipe Joint...	13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-9A



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 201.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 204.6 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-9



Pipe Segment Refere...	City	Street	Material		Location C...	Sewer Use
E6-9A_E6-9	Oliver Springs	Easement	PolyVinyl Chloride		Parking Lo...	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
E6-9A	204.6		Circular		Church Parking Lot	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...	
E6-9	204.6		8	8	13	
SPR	N/A	MPR	PO Number		Customer	
			4397-03		GRW	
SPRI	N/A	MPRI	Work Order		Purpose	
			4397-02		Pre-Rehabilitation Survey	
QSR	N/A	QMR				
OPR	Surveyed By	Direction	Date		Media label	
N/A	Barry_Rogers	Downstream	20150615			
OPRI	Certificate Number	Pre-Cleaning	Time		Weather	
N/A	U-1012-16405	Jetting	09:26		Very Dry	
Date Cleaned			End Time		Additional Info	
20150615			09:36			

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div><div>Code</div><div>ID</div><div>Length</div></div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Subtotals			0		Subtotals	0		Subtotals	0		
SUMMARY			Pipe Rating	0	Pipe Rating	0	Overall Pipe Rating	0			
			Structural Index	0	O&M Index	0	Overall Index	0			
			Str. Quick Rating	0000	O&M Quick Rating	0000	Ovrl. Quick Rating	0000			