



Defect Listing

Pipe Segment Refere... E7-3_E7-4	City Oliver Springs	Street Parking Lot	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E7-3	Total Length 104.1	Year Laid	Shape Circular	Location Details Off Hwy 62	
DS Manhole E7-4	Length surveyed 104.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150615	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:25	Weather Very Dry	
Date Cleaned 20150615			End Time 12:30	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E7-3									
0.0 ft.	Water Level				0	<input type="checkbox"/>			
101.1 ft.	Water Level				5	<input type="checkbox"/>			
104.1 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E7-4									




Image Report 4/Page


Pipe Segment Refere... E7-3_E7-4	City Oliver Springs	Street Parking Lot	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E7-3	Total Length 104.1	Year Laid	Shape Circular		Location Details Off Hwy 62	
DS Manhole E7-4	Length surveyed 104.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E7-3



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 101.1 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 104.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E7-4



Pipe Segment Refere... E7-3_E7-4	City Oliver Springs	Street Parking Lot	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E7-3	Total Length 104.1	Year Laid	Shape Circular		Location Details Off Hwy 62	
DS Manhole E7-4	Length surveyed 104.1	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150615		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:25		Weather Very Dry	
Date Cleaned 20150615			End Time 12:30		Additional Info	

Page #: 3