



Defect Listing

Pipe Segment Refere... E7-4_E7-5	City Oliver Springs	Street ParkingLot	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E7-4	Total Length 141.2	Year Laid	Shape Circular	Location Details Off side of HWY 61	
DS Manhole E7-5	Length surveyed 141.2	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150615	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:55	Weather Very Dry	
Date Cleaned 20150615			End Time 13:08	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E7-4									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
141.0 ft.	Water Level				5	<input type="checkbox"/>			
141.2 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E7-5									




Image Report 4/Page

Pipe Segment Refere... E7-4_E7-5	City Oliver Springs	Street ParkingLot	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E7-4	Total Length 141.2	Year Laid	Shape Circular		Location Details Off side of HWY 61	
DS Manhole E7-5	Length surveyed 141.2	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E7-4



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 141.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 141.2 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E7-5



Pipe Segment Refere... E7-4_E7-5	City Oliver Springs	Street ParkingLot	Material PolyVinyl Chloride		Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E7-4	Total Length 141.2	Year Laid	Shape Circular		Location Details Off side of HWY 61	
DS Manhole E7-5	Length surveyed 141.2	Year Renewed	Height 8	Width 8	Pipe Joint...	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150615		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:55		Weather Very Dry	
Date Cleaned 20150615			End Time 13:08		Additional Info	

Page #: 3