



Defect Listing

Pipe Segment Refere... E8-1_E6-5	City Oliver Springs	Street Hwy 61	Material PolyVinyl Chloride	Location C... Parking Lo...	Sewer Use Sanitary
Upstream MH E8-1	Total Length 317.2	Year Laid	Shape Circular	Location Details Church Parking Lot	
DS Manhole E6-5	Length surveyed 317.2	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR 8	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2.7	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 4122		
OPR 8	Surveyed By Barry Rogers	Direction Downstream	Date 20150616
OPRI 2.7	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:49
	Date Cleaned 20150616	End Time 08:22	Weather Very Dry
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E8-1									
0.0 ft.	Water Level				0	<input type="checkbox"/>			
303.6 ft.	Water Level Sag				15	<input type="checkbox"/>			2
310.0 ft.	Water Level Sag				30	<input type="checkbox"/>			2
316.0 ft.	Camera Underwater				0	<input type="checkbox"/>			4
317.2 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: E6-5									




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E8-1_E6-5	Oliver Springs	Hwy 61	PolyVinyl Chloride	Parking Lo...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E8-1	317.2		Circular	Church Parking Lot	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E6-5	317.2		8	8	13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E8-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 303.6 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A




Distance: 310.0 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E8-1_E6-5	Oliver Springs	Hwy 61	PolyVinyl Chloride	Parking Lo...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E8-1	317.2		Circular	Church Parking Lot	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E6-5	317.2		8	8	13



Distance: 316.0 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A



Distance: 317.2 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E6-5



Albuquerque, NM

SPR	N/A	MPR	8	PO Number 4397-03		Customer			
SPRI	N/A	MPRI	2.7			GRW			
QSR	N/A	QMR	4122	Work Order 4397-02		Purpose			
						Pre-Rehabilitation Survey			
OPR 8		Surveyed By Barry_Rogers		Direction Downstream		Date 20150616		Media label	
OPRI 2.7		Certificate Number U-1012-16405		Pre-Cleaning Jetting		Time 07:49		Weather Very Dry	
Date Cleaned 20150616						End Time 08:22		Additional Info	

Page 1 of 1