

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

/ - 000 002 500 Nº 000587

APPLICATION FOR SEWER PERMIT	
Permit No Date 900. 13,1985	
Permit Void 90 days from Date of Issuance	
Owner Name Bob Anigo	
Property Address 102 minden Bd	
Lot # P.O. Box	
Town Cagalls , IN Zip Code 46048	
Phone Water Meter	
\$	
\$	
Application is hereby made for connection to the Fall Creek Regional Waste District Sewer System for the above listed property - Permit Type: Residential, Commercial, Industrial, or Governmental/ Institutional User Information	
All workmanship and materials shall conform to the standards of the District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced at the owners expense.	
The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner.	
I have read and fully understand the above provisions and agree to comply by said provisions.	
(A) (COLCY COLCANT (S) SIGNATURE ***********************************	

Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 "	
Type Pipe Pipe PVC INSPECTOR Rom Rejected Rejected Rejected Rejected Rejected Rejected Rejected Rejected Notes:	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PVC Basement Yes No X	
Date inspected j-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PVC Basement Yes No X Sump Pump Yes No X	
Date inspected -14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Approved Rejected Notes: Size Pipe 6	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PVC Basement Yes No X Sump Pump Yes No X Downspout to Ground Yes X No Septic Tank Pumped & filled Yes X No	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PVC Basement Yes No X Sump Pump Yes No X Downspout to Ground Yes X No Septic Tank Pumped & filled Yes X No	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe	
Date inspected 1-14-86 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe	