

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

hen

2P1	2,000 3803.00
(a)	Nº 001680
APPLICATION	N FOR SEWER PERMIT
Permit No.	Date 6-27-89
ermit Void 90 days from Date po	f Issuance
wner Name Blow J	rulding Corp (643-0330)
Property Address 1222	Gellow Brick
ot # 86	V P.O. Box
rown Rendleton	, IN Zip Code 46064
Phone	Water Meter
2880.00 Tap on Fee	Paid
as as oo Inspection	
Waste District Sewer System for	for connection to the Fall Creek Regional the above listed property - Permit Type:, Industrial, or Governmental/ formation
District Ordinance as described Acceptance and approval must be authorized representative befor to the main sewer lines. Any v	als shall conform to the standards of the in Ordinance 84-2 and 84-3 as amended. made by the District inspector or his duly e backfilling and final connection is made iolation of applicable regulations will es in violation to be removed and replaced
approval of materials, and inst	aste District is responsible for the inspection, callation techniques only. All costs for any liabilities resulting from same is the perty owner.
I have read and fully under comply by said provisions. Michael Applica	erstand the above provisions and agree to
	INSPECTOR
Date inspected 8-4-89 Appro	oved Rejected
Reason for rejection	
Date reinspected	Approved Rejected
Notes: Size Pipe 4'	North
Type Pipe PC SDR35	North
Basement Yes No	
Sump Pump Yes No	E/EC LINE
Downspout to Ground Yes/No	_
Septic Tank Pumped & filled Yes	
	s No

Rev. 11/84

Special Conditions NO Septic TANK. High Ground.

weter under house.

DriVEWAY