129 or 131?



FALL CREEK REGIONAL WASTE DISTRICT 131-3-06361.01

Box 44, Pendleton, Indiana 46064

rextal

| | Nº 001792 | |
|---|---|-------|
| APPLICATION FOR SEW | ER PERMIT | |
| Permit No Date | - June 1 | |
| Permit Void 90 days from Date of Issuanc | e | |
| Owner Name | I listley | |
| Property Address/ 131 UNIC | 9 Willt V | |
| Lot # 131 P.6. | Zip Code 46064 | |
| Phone 778-440/ Wate | | |
| | I PIGGGI | |
| \$ | | |
| \$ 25.00 Inspection fee paid | | |
| Application is hereby made for conn Waste District Sewer System for the abov Residential , Commercial , Ind Institutional . User Information | e listed property - Permit Type: ustrial, or Governmental/ | |
| All workmanship and materials shall District Ordinance as described in Ordin Acceptance and approval must be made by authorized representative before backfil to the main sewer lines. Any violation cause all lines and appurtenances in vio at the owners expense. | ance 84-2 and 84-3 as amended. the District inspector or his duly ling and final connection is made of applicable regulations will | |
| The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner. | | |
| I have read and fully understand the above provisions and agree to comply by said provisions. | | |
| APPLICATE (S) SIGNATURE | | |
| INSPECTOR T | | |
| Date inspected 7-11-9 Approved Rejected | | |
| Reason for rejection | | |
| | | |
| Date reinspectedAp | proved Rejected | |
| Notes: Size Pipe 8" | | • |
| Type Pipe PVC SOR 35 | | North |
| Basement Yes No | | |
| Sump Pump Yes No | | |
| Downspout to Ground Yes No | | |
| Septic Tank Pumped & filled Yes No | | |
| Contractor J A | K | |
| Special Conditions | 0 | |
| | 8°c.0. | |
| | | |
| | | / |
| | | |
| | | |
| /84 | | |