add order on file



FALL CREEK REGIONAL WASTE DISTRICT 9378 S. 650 West PO Box 59 Pendleton, IN 46064-0059 778-7544 Pendleton, IN

13-50578.00

Nto 0700	
APPLICATION FOR SEWER PERMIT Nº 2389	
Date7/10/94	
Permit Void 90 days from Date of Issuance	
Owner Name Crossmann Comm, Robert Green	
Property Address 170 (anterny Ko	
Lot # 5/ Country Fame 0. Box	
Town lendle for , IN zip code 46044	
Phone (3/1) 573-8683 City Water Well	
\$ 700.00 Tap on Fee Paid	
\$Inspection fee paid	
Application is hereby made for connection to the Fall Creek Regional Waste District Sewer System for the above listed property - Permit Type: Residential, Commercial, Industrial, or Governmental/Institutional	
All workmanship and materials shall conform to the standards of the District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced	
at the owners expense.	
The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner.	
I have read and fully understand the above provisions and agree to	
applicant(s) signature	
APPLICANT(S) SIGNATURE	
APPLICANT(S) SIGNATURE	
APPLICANT(S) SIGNATURE  INSPECTOR IM	
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 8-27-96 Approved Rejected	
APPLICANT(S) SIGNATURE  INSPECTOR IM	
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 8-27-96 Approved Rejected	
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 3-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected	*
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 3-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 8-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6" "	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 3-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6" "  Type Pipe SDR 35"	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 3-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6" "  Type Pipe SDR 35"  Basement Yes No	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 8-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6" " Type Pipe SDR 35"  Basement Yes No  Sump Pump Yes No  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 3-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6"  Type Pipe SDR 35"  Basement Yes No  Sump Pump Yes No  Downspout to Ground Yes No	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 8-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6" " Type Pipe SDR 35"  Basement Yes No  Sump Pump Yes No  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 8-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe " Type Pipe SDR 35  Basement Yes No  Sump Pump Yes No  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No  Contractor Qw Watton Cout	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 3-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6" "  Type Pipe SDR 35"  Basement Yes No Sump Pump Yes No Septic Tank Pumped & filled Yes No Contractor 6 Watson Court  Special Conditions SAA  Existing Home	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 2-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6' "  Type Pipe SDR 35  Basement Yes No  Sump Pump Yes No  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No  Contractor QW Watson Count  Special Conditions SAL	North
APPLICANT(S) SIGNATURE  INSPECTOR IM  Date inspected 3-27-96 Approved Rejected  Reason for rejection  Date reinspected Approved Rejected  Notes: Size Pipe 6" "  Type Pipe SDR 35"  Basement Yes No Sump Pump Yes No Septic Tank Pumped & filled Yes No Contractor 6 Watson Court  Special Conditions SAA  Existing Home	North