

Permit No.

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064 22-18480.

2-00/8480.00

APPLICATION FOR SEWER PERMIT

Nº 000414

Owner Name		
7 -	DORDey 22-18480.00	
Property Address 0 540	WORK & 194 E. 500 SOUT	H
Lot # P.O	. Box	
Town anderson, IN	Zip Code 46013	
Phone 643-2458 Wat	er Meter"	
\$ 15000 Tap on Fee Paid		
\$ 2500 Inspection fee pair	d	
Application is hereby made for con Waste District Sewer System for the aboresidential, Commercial, Interestitutional User Information	dustrial, or Governmental/	
All workmanship and materials shal District Ordinance as described in Ordi Acceptance and approval must be made by authorized representative before backfi to the main sewer lines. Any violation cause all lines and appurtenances in viat the owners expense.	nance 84-2 and 84-3 as amended. the District inspector or his duly lling and final connection is made of applicable regulations will	
The Fall Creek Regional Waste Dist approval of materials, and installation materials and installation and any liab sole responsibility of the property own	pilities resulting from same is the	
comply by said provisions. APPLICANT(S) SI ***********************************	PR	
Reason for rejection		
Date reinspected A	approved Rejected	
	approved Rejected	North
Date reinspected A	approved Rejected	North
Date reinspected A Notes: Size Pipe "	approved Rejected	North
Date reinspected A Notes: Size Pipe " Type Pipe	approved Rejected	North
Date reinspected A Notes: Size Pipe " Type Pipe Basement Yes No	approved Rejected	North
Date reinspected A Notes: Size Pipe " Type Pipe Basement Yes No Sump Pump Yes No	approved Rejected	North
Date reinspected A Notes: Size Pipe " Type Pipe Basement Yes No Sump Pump Yes No Downspout to Ground Yes No	approved Rejected	North
Date reinspected A Notes: Size Pipe " Type Pipe " Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No	approved Rejected	North
Date reinspectedA Notes: Size Pipe" Type Pipe" Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor	approved Rejected	North
Date reinspectedA Notes: Size Pipe" Type Pipe" Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor	approved Rejected	North
Date reinspectedA Notes: Size Pipe" Type Pipe" Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor	approved Rejected	North
Date reinspectedA Notes: Size Pipe" Type Pipe" Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor	approved Rejected	North
Date reinspectedA Notes: Size Pipe" Type Pipe" Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor	Approved Rejected	North
Date reinspectedA Notes: Size Pipe" Type Pipe" Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor	approved Rejected	North