add aber mfile



Rev. 11/84

FALL CREEK REGIONAL WASTE DISTRICT Box 44, Pendleton, Indiana 46064

APPLICATION	FOR SEWER PERMIT Nº 001931
Permit No.	Date 6-30-93
Permit Void 90 days from Date of	Issuance
Owner Name Deluse	200
Property Address 1 Villac	e Park (120
	P.O. Box
Town rend eton	IN Zip Code III
Phone	Water Meter "
\$	id.
\$ 25 00 Inspection fe	
Institutional User Inform	r connection to the Fall Creek Regional a above listed property - Permit Type: _, Industrial, or Governmental/ mation
All workmanship and materials District Ordinance as described in Acceptance and approval must be mad authorized representative before bas to the main sever bas	shall conform to the standards of the Ordinance 84-2 and 84-3 as amended.
The Fall Creek Regional Waste I approval of materials, and installat materials and installation and any 1 sole responsibility of the property	District is responsible for the inspection, tion techniques only. All costs for tiabilities resulting from same is the owner.
comply by said provisions	d the above provisions and agree to
T. Phyle	7
APPLICANT(S) SIGNATURE	
*********	*****
Date inspected 9-10-93 Approved Reason for rejection	TOR 11M
Reason for rejection	Rejected
Date reinspected	
	Approved Rejected
Size Pipe	
Type Pipe SDR 35 Basement Yes No	MH
Sump Deeres in	North
Downspout to Ground Yes No	
Septic Tank Pumped & filled Yes No	
Contractor Watson. Brothers.	
Special Conditions NEW HOME	26" C.O.
A.	9
	\wedge