



FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

D. Lineberry
2076 W. US 36

22-01280.00

22-

APPLICATION FOR SEWER PERMIT

Nº 001825

Permit No. _____ Date 1/2/92

Permit Void 90 days from Date of Issuance

Owner Name Fred Merrill

Property Address 2076 2073 St Rd 36 *across from Regency Insulation*

Lot # _____ P.O. Box _____

Town _____, IN Zip Code 46064

Phone _____ Water Meter _____"

\$ 500.00 Tap on Fee Paid

\$ 2500 Inspection fee paid

Application is hereby made for connection to the Fall Creek Regional Waste District Sewer System for the above listed property - Permit Type: Residential ☒, Commercial _____, Industrial _____, or Governmental/Institutional ☒. User Information _____.

All workmanship and materials shall conform to the standards of the District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced at the owners expense.

The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner.

I have read and fully understand the above provisions and agree to comply by said provisions.

Fred J Merrill
APPLICANT(S) SIGNATURE

INSPECTOR *B*

Date inspected 3-18-92 Approved _____ Rejected ☒

Reason for rejection _____

Date reinspected _____ Approved _____ Rejected _____

Notes:

Size Pipe 6-0 is 6"

Type Pipe PUL

Basement Yes _____ No ☒

Sump Pump Yes _____ No ☒

Downspout to Ground Yes ☒ No _____

Septic Tank Pumped & filled Yes _____ No ☒

Contractor unknown

Special Conditions FCRD can not

approve with out seeing job
Before covering

clean out cap is on y connection
we require T
clean-out installed in AREA
that will be under front porch
contractor Did not Call for
inspection

North

