

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

22-00 940.00

ADDITION FOR SEWER DERMIT

Nº 000431

III I DAVIA TON	TON DEHILL THEFT
Permit No.	Date 0 29 85
Permit Void 90 days from Date of	Issuance
Owner Name	n. Shull
Property Address RR 4	BIOX (01 2311 W US 36
Lot #	P.O. Box
	, IN Zip Code 46064
	Water Meter
\$ 15000 Tap on Fee I	
2500	
\$ Inspection f	fee paid
Waste District Sewer System for t Residential X , Commercial	for connection to the Fall Creek Regional the above listed property - Permit Type:, Industrial, or Governmental/ ormation
District Ordinance as described in Acceptance and approval must be mauthorized representative before to the main sewer lines. Any vice	Is shall conform to the standards of the in Ordinance 84-2 and 84-3 as amended. made by the District inspector or his duly backfilling and final connection is made plation of applicable regulations will s in violation to be removed and replaced
approval of materials, and instal	te District is responsible for the inspection, llation techniques only. All costs for my liabilities resulting from same is the rty owner.
I have read and fully unders comply by said provisions.	stand the above provisions and agree to
X Japan M. Sha	(S) SIGNATURE
******************	**************************************
TN	NSPECTOR Ben
Date inspected 11-8-85	ed Rejected
Reason for rejection	Rejected
Reason for rejection	
Date and a second	
Date reinspected	Approved Rejected
Notes: Size Pipe "	*
Size Pipe "Type Pipe "	North
Basement Yes No X	
Sump Pump Yes No X	
Downspout to Ground Yes XNo	
Septic Tank Pumped & filled Yes	w.×
Contractor A+A	1100
Special Conditions	
4	