

FALL CREEK REGIONAL WASTE DISTRICT 9378 S. 650 West PO Box 59 Pendleton, IN 46064-0059 778-7544

Nº 2202

Permit Void 90 days from Owner Name GAI	Date 0-1-95		
Owner Name GAI	Date of Issuance		
	Ry Condon		
Property Address 33	32 W. State St.		
	P.O. Box		
TOWN Pendleton	, IN Zip Code 46064		
Phone	City Water $\chi$ Well		
\$NA	on Fee Paid lateral replacement		
\$ Insp	pection fee paid		
Application is hereby made for connection to the Fall Creek Regional Waste District Sewer System for the above listed property - Permit Type: Residential, Commercial, Industrial, or Governmental/ Institutional User Information  All workmanship and materials shall conform to the standards of the District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced at the owners expense.  The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner.			
		comply by said provisions	y understand the above provisions and agree to .
		Al	PPLICANT(S) SIGNATURE
Al	************		
*********	**************************************		
Date inspected 6-1-95	**************************************		
Date inspected 6-1-95	**************************************		
Date inspected 6-1-95 Reason for rejection	**************************************		
Date inspected 6-1-95 Reason for rejection	INSPECTOR Rejected  Approved Rejected		
Date inspected 6-1-95 Reason for rejection Date reinspected	INSPECTOR Rejected  Approved Rejected		
Date inspected 6-1-95 Reason for rejection Date reinspected	INSPECTOR Rejected  Approved Rejected		
Date inspected 6-1-95 Reason for rejection  Date reinspected  Date reinspected  Date Pipe 6  Date Pipe 9 V	INSPECTOR Rejected  Approved Rejected		
Date inspected 6-1-95 Reason for rejection Date reinspected Date reinspected Date Pipe 6 Date Pipe 7 V Date Pipe 7	**************************************		
Date inspected 6-1-95 Reason for rejection  Date reinspected  Date reinspected  Date Pipe  Date Pip	**************************************		
Date inspected 6-1-95 Reason for rejection  Date reinspected  Date	Approved Rejected  Approved Rejected  Approved Rejected		
Cate inspected 6-1-95 Reason for rejection  Cate reinspected  Cotes: Cize Pipe  Cype Pip	Approved Rejected  Approved Rejected  Approved Rejected		
Date inspected 6-1-95 Reason for rejection  Date reinspected  Date	Approved Rejected  Approved Rejected  No ed Yes No  No  Rejected		
Date inspected 6-1-95 Reason for rejection  Date reinspected  Date	Approved Rejected  Approved Rejected  No ed Yes No  No  Rejected		
Cate inspected 6-1-95 Reason for rejection  Cate reinspected  Cotes: Cize Pipe Cype Pipe Cype Pipe Casement Yes  Cownspout to Ground Yes  Contractor Jim Bake  Cypecial Conditions	Approved Rejected  Approved Rejected  No ed Yes No  No  Rejected		