<485-5691

## 546-0454-Ulam FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

	1-00072	45
	Nº 001636	
APPLICATION FOR SEWER		
No Date	3-17-88	
Void 90 days from Date of Issuance	V	
Name DONN + 1	Taken Ulam	
ty Address 416 N A	I fonte St	
P.O. Bo	x	
Ingalls , IN Zi	p Code 46048	
Water M	eter Izgalls "	
500.00 Tap on Fee Paid		
25.00 Inspection fee paid		
Application is hereby made for connect District Sewer System for the above 1 ential, Commercial, Industrutional User Information	isted property - Permit Type: rial, or Governmental/	
All workmanship and materials shall content of the	e 84-2 and 84-3 as amended. District inspector or his duly g and final connection is made applicable regulations will	
The Fall Creek Regional Waste District val of materials, and installation ted ials and installation and any liability responsibility of the property owner.  I have read and fully understand the any by said provisions.	hniques only. All costs for ies resulting from same is the	
Baren J. Blam		
Baren 5. Illam APPLICANT (S) SIGNAT		
**************************************	******************	
inspected 3-21-88 Approved	Rejected	
**************************************	Rejected	
inspected 3-21-88 Approved	Rejected	
inspected 3.21-88 Approved	Rejected	
inspected 3-21-88 Approved	Rejected	
inspected 3.2/18 Approved  inspected Approved  reinspected Approved	Rejected	1
inspected 3.21-88 Approved INSPECTOR Approved Pipe 4 "Pipe 4 "Pipe 4 "	Rejected	1
inspected 3.2188 Approved INSPECTOR Inspected Approved Pipe 4 "Pipe NoX	Rejected	
inspected 3.2188 Approved  inspected 3.2188 Approved  reinspected Approved  Pipe 4 "  Pipe 4 "  Pipe 5 (C  Pump Yes No X	Rejected	1
inspected 3.21-88 Approved  inspected Approved  reinspected Approved  Pipe 4 "  Pipe 4 "  Pipe 5 (C  Pump Yes No X  Poout to Ground Yes No	Rejected	1
INSPECTOR  Inspected 3.2188 Approved  in for rejection  reinspected Approved  Pipe 4 "  Pipe 4 "  Pipe V C  Pump Yes No X  Pount to Ground Yes No  C Tank Pumped & filled Yes No	Rejected	
inspected 3.2188 Approved  inspected 3.2188 Approved  for rejection  reinspected Approved  Pipe 6 "  Pipe 7 (C  ent Yes No X  pout to Ground Yes No  c Tank Pumped & filled Yes No X  actor 1 (Son Counce)	Rejected	
INSPECTOR  Inspected 3.2188 Approved  in for rejection  reinspected Approved  Pipe 4 "  Pipe 4 "  Pipe V C  Pump Yes No X  Pount to Ground Yes No  C Tank Pumped & filled Yes No	Rejected	
inspected 3.2188 Approved  inspected 3.2188 Approved  for rejection  reinspected Approved  Pipe 6 "  Pipe 7 (C  ent Yes No X  pout to Ground Yes No  c Tank Pumped & filled Yes No X  actor 1 (Son Counce)	Rejected	
inspected 3.2188 Approved  inspected 3.2188 Approved  for rejection  reinspected Approved  Pipe 6 "  Pipe 7 (C  ent Yes No X  pout to Ground Yes No  c Tank Pumped & filled Yes No X  actor 1 (Son Counce)	Rejected	1