

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

22-0019240.00

Nº 001490 APPLICATION FOR SEWER PERMIT _____ Date _____ 4-14-86 Permit Void 90 days from Date of Issuance Owner Name Cletis BRONNEN berg Property Address 7329 Columbus Ave 4649 SSR 109

Lot # P.O. Box Changed to 4649 S Mew Phone 6449 - O768 Water Meter "Columbus Road"

Columbus Road 50.00 Tap on Fee Paid) Inspection fee paid Application is hereby made for connection to the Fall Creek Regional Waste District Sewer System for the above listed property - Permit Type:
Residential , Commercial , Industrial , or Governmental/
Institutional . User Information . . User Information All workmanship and materials shall conform to the standards of the District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced at the owners expense. The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner. I have read and fully understand the above provisions and agree to comply by said provisions. APPLICANT(S) SIGNATURE INSPECTOR B Date inspected 4-17-86 Approved V Rejected Reason for rejection Rejected Date reinspected Approved Size Pipe ____ Type Pipe PUC Basement Yes No X Sump Pump Yes No X Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Pico Contractor Special Conditions