

## FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

	1-0002987.00
	Nº 001488
APPLICATION FOR SI	EWER PERMIT
Permit No Da	te 4-14-86
Permit Void 90 days from Date of Issua	nce
Owner Name William	Kersor
Property Address 476	BROADWAY
Lot # P.(	O. Box
Town <i>IN9a115</i> , II	0. Box  N Zip Code 46048  ter Meter 20 "
Phone 485-4364 Wat	ter Meter"
S 50°0 Tap on Fee Paid	•
• • • • • • • • • • • • • • • • • • • •	
\$ 25 are Inspection fee par	id
Application is hereby made for con Waste District Sewer System for the above Residential, Commercial, In Institutional, User Information	ndustrial , or Governmental/
	ll conform to the standards of the inance 84-2 and 84-3 as amended. y the District inspector or his duly illing and final connection is made n of applicable regulations will
approval of materials, and installation materials and installation and any liabsole responsibility of the property own.  I have read and fully understand comply by said provisions.	bilities resulting from same is the mer.
Genda Tea	sor
APPLÍCANT(S) S:	IGNĀTURE
*************	
INSPECTO	OR KA-) Y
Date inspected 7-31-86 Approved	X Rejected
Reason for rejection	
	Approved Rejected
Notes: Size Pipe "	
Type Pipe Puc	Noi
Basement Yes No 🗙	
<del></del>	1 (
Sump Pump Yes No X	
Sump Pump Yes No X	To City
Sump Pump Yes No X  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No X	φιίο
Sump Pump Yes No X  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No X  Contractor / 2 ~ 1 S	Φ6'c0
Sump Pump Yes No X  Downspout to Ground Yes No	\$745°
Sump Pump Yes No X  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No X  Contractor / ( ) ( )  Special Conditions Own w ///	\$75° C
Sump Pump Yes No X  Downspout to Ground Yes No  Septic Tank Pumped & filled Yes No X  Contractor / ( ) ( )	\$75° \$75° \$75°