

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

2-00/5900

	ON FOR SEWER PERMIT	Nº 000916
Permit No.	Date 12-9-85	
Permit Void 90 days from Date		
Owner Name BETTV	J. BROWN	
Property Address 7617	MAIN ST - 5057	1 S. 50 %.
	P.O. Box	
	, IN Zip Code _460//	
Phone 642-1841		"
\$ <u>150,00</u> Tap on Fee \$ <u>25,00</u> Inspection		
3 Inspection	n lee palo	
Waste District Sewer System for Residential, Commercial	e for connection to the Fall Creek r the above listed property - Perm , Industrial, or Govern nformation	nit Type: mental/
	ials shall conform to the standard d in Ordinance 84-2 and 84-3 as an	

District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced at the owners expense.

The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner.

I have read and fully understand the above provisions and agree to comply by said provisions.

Jerry W Co	A FOR Belly LICANT (S) SIGNATURE	J. Brown	
The inspected 12-9-85A Reason for rejection	INSPECTOR	**************************************	
Date reinspected	Approved	Rejected	
Size Pipe" Type Pipe" Basement Yes No X Sump Pump Yes No X	Ĩ		North

Downspout to Ground Yes X No Septic Tank Pumped & filled Yes No Contractor Special Conditions