

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

1-0000145.00

	R SEWER PERMIT	
	N; 000851	
Permit No.		
Permit Void 90 days from Date of Iss		
Owner Name Lillus Pe Property Address 609 Cas	+tigRew	
Property Address 009 Cas	st Ot.	
Lot #	P.O. Box	
Town Ingalls.	IN Zip Code 46048 Water Meter "	
Phone 485-4471	Water Meter	
\$ /5000 Tap on Fee Paid		
\$ 2500 Inspection fee	paid	
Waste District Sewer System for the Residential Commercial , Institutional . User Informa	tion	
District Ordinance as described in O Acceptance and approval must be made authorized representative before bac to the main sewer lines. Any violat	by the District inspector or his duly kfilling and final connection is made	
approval of materials, and installat materials and installation and any l sole responsibility of the property	iabilities resulting from same is the owner.	
comply by said provisions.	ad the above provisions and agree to	
the state of the s	24 strout X nues	
APPLICANT(S)	SIGNATURE TO STORY	
APP/ICANT(S)	SIGNATURE ************************************	
APPICANT(S)	SIGNATURE ***********************************	
APPICANT(S)	******	
APPICANT(S)	**************************************	
APPLICANT(S) ***********************************	**************************************	
APPLICANT(S) ***********************************	**************************************	
APPLICANT(S) ***********************************	CTOR CON Rejected	
APPLICANT(S) ***********************************	CTOR CON Rejected	th
APPLICANT(S) ***********************************	Rejected Rejected Approved Rejected	th
APPECANT(S) ******** INSPE Date inspected 6-18-86 Approved Reason for rejection Date reinspected Notes: Size Pipe " Type Pipe Basement Yes No X	Rejected Rejected Approved Rejected	th
APPEICANT(S) ********** INSPE Date inspected 6-18-86 Approved Reason for rejection Date reinspected Notes: Size Pipe 6 " Type Pipe 80 Sump Pump Yes No X	Rejected Rejected Approved Rejected	th
APPLICANT(S) *********** INSPE Date inspected 6-18-86 Reason for rejection Date reinspected Notes: Size Pipe " Type Pipe " Basement Yes No X Sump Pump Yes No X Downspout to Ground Yes X No	Rejected Rejected North	th
APPLICANT(S) ********* INSPE Date inspected 6-18-86 Approved Reason for rejection Date reinspected Notes: Size Pipe " Type Pipe Basement Yes No X Sump Pump Yes No X Downspout to Ground Yes X No Septic Tank Pumped & filled Yes X No	Rejected Rejected North	th
APPLICANT(S) ***********************************	Rejected Rejected North	th
APPLICANT(S) ***********************************	Rejected Rejected North	th
APPLICANT(S) ***********************************	Rejected Rejected North	th
APPLICANT(S) ***********************************	Rejected Rejected North	th
APPLICANT(S) ***********************************	Rejected Rejected North	hth
APPLICANT(S) ***********************************	Rejected Rejected North	hth