

FALL CREEK REGIONAL WASTE DISTRICT

/or /: 30

Box 44, Pendleton, Indiana 46064

| | | | 2-001: | 5400. | 00 |
|---|--|--|--|------------------------------|-------|
| | APPLICATION FOR SEW | ER PERMIT | Nº 00 | 1252 | |
| Permit No. | Date | 1-, | 24-86 | | |
| | | | | | |
| Owner Name | harles 6 7313 Pla | DUR. tte. | | | |
| Property Address | 7313 Pla | anto fine | DR | | |
| | | | | | |
| TOWN ANDE | P.O. RSON, IN | Zip Code 4 | 6013 | | |
| Phone 64 | 2-9318 Wate | r Meter | | | |
| | | | | | |
| \$ | Tap on Fee Paid | | | | |
| \$\$ | Inspection fee paid | | | | |
| Waste District Sewe Residential Institutional All workmanshi District Ordinance Acceptance and appr authorized represent to the main sewer 1 | hereby made for connect r System for the above Commercial, Inde User Information p and materials shall as described in Ordina oval must be made by tative before backfill ines. Any violation of appurtenances in vio | e listed proper ustrial, conform to the ance 84-2 and 8 the District in ling and final of applicable r | ty - Permit Type or Governmental, standards of th 4-3 as amended. spector or his of connection is ma egulations will | e: / ne duly ade | |
| approval of materia materials and insta sole responsibility | Joute | techniques only lities resultir r. e above provisi | . All costs fo ag from same is | r the | |
| | APPLICANT(S) SIG | | | | |
| Date inspected <u>3</u> - Reason for rejectio | INSPECTOR 18-86 Approved | Rejec | ted | | |
| Date reinspected | Ap | proved | Rejected | | |
| Notes: Size Pipe Type Pipe Basement Yes | | | | | North |
| | | | - | | |
| Sump Pump Yes N Downspout to Ground | | Ĩ | 7 | | |
| Septic Tank Pumped | | | 1 | | |
| Contractor | | 1 | | | |
| Special Conditions | | | | | |
| 49 | 68 | | 0 | | - |