

## FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

|   | 2.0008840.00                     |
|---|----------------------------------|
|   | Nº 000548                        |
| APPLICATION FOR SEWER   | PERMIT                           |
| Permit No Date  | nov. 11,1985                     |
| Permit Void 90 days from Date of Issuance   |                                  |
| Owner Name Clork Crico  | lerson                           |
| Property Address 732 Sloc   | & Drive                          |
| Lot # P.O. B  | ox                               |
| Town anderson, IN Z   | ip Code 46013                    |
| Phone 693-7975 Water  | Meter                            |
| \$ Tap on Fee Paid  |                                  |
| \$ 2500 Inspection fee paid   |                                  |
|   | tion to the Dell Guesh Designed  |
| Application is hereby made for connec<br>Waste District Sewer System for the above      |                                  |
| Residential , Commercial , Indus<br>Institutional . User Information                    | trial, or Governmental/          |
|   |                                  |
| All workmanship and materials shall c<br>District Ordinance as described in Ordinan     |                                  |
| Acceptance and approval must be made by th  | e District inspector or his duly |
| authorized representative before backfilli<br>to the main sewer lines. Any violation of |                                  |
| cause all lines and appurtenances in viola  |                                  |
| at the owners expense.  |                                  |
| The Fall Creek Regional Waste Distric<br>approval of materials, and installation te     |                                  |
| materials and installation and any liabili  | ties resulting from same is the  |
| sole responsibility of the property owner.  |                                  |
| I have read and fully understand the  | above provisions and agree to    |
| comply by said provisions.  |                                  |
| X Clark A Merson<br>APPLICANT (S) SIGNA   |                                  |
| **************************************  | TORE                             |
| INSPECTOR   | (Ha)                             |
| Date inspected 11-26-85 Approved  | Rejected                         |
| Reason for rejection  |                                  |
|   |                                  |
| Date reinspected Appr   | coved Rejected                   |
| Notes:<br>Size Pipe 6 "   | *                                |
| Type Pipe PUC   | North                            |
| Basement Yes No X   |                                  |
| Sump Pump Yes No Y  |                                  |
| Downspout to Ground Yes $\chi$ No   |                                  |
| Septic Tank Pumped & filled Yes $X$ No  |                                  |
| Contractor Delp   |                                  |
| Special Conditions  |                                  |
|   |                                  |
|   |                                  |
| $\cap$  |                                  |
| 6   | <                                |
| <i>C</i> ,  |                                  |