

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

22-04680.00

| | | 2-000 4680.0 | 00 |
|--|--|---|----|
| APPLICATI | ON FOR SEWER PERMIT | Nº 00005 | 57 |
| Permit No. | Date 12 | 117/85 | |
| Permit Void 90 days from Date | of Issuance | | 06 |
| Owner Name GARI GARI | INR | 800 W 51 | 5) |
| roperty Address | BOX 209 AA | | |
| ot # | P.O. Box | | |
| rown TANDLATON, | , IN Zip Code | 46064 | |
| Phone 778-7226 | Water Meter _ | " | |
| Tap on Fe | e Paid | | |
| 25 SO Inspectio | n fee paid | | |
| | | | |
| Application is hereby mad Waste District Sewer System for Residential, Commercial User I | r the above listed p | property - Permit Type: | |
| All workmanship and mater District Ordinance as describe Acceptance and approval must be authorized representative befor to the main sewer lines. Any cause all lines and appurtenant at the owners expense. | d in Ordinance 84-2 e made by the Distri re backfilling and violation of applica | and 84-3 as amended. ict inspector or his duly final connection is made able regulations will | |
| The Fall Creek Regional Wapproval of materials, and installation and sole responsibility of the profit in the prof | stallation technique lany liabilities re perty owner. | s only. All costs for sulting from same is the | |
| ******** | | ****** | |
| | INSPECTOR BON | | |
| Date inspected 12-21-85 Appr | oved | Rejected | |
| Reason for rejection | | | |
| | | | |
| Date reinspected | Approved | Rejected | |
| Notes: Size Pipe (" | | | |
| Type Pipe PUC " | | | |
| Basement Yes No Y | | | |
| Sump Pump Yes No | | | , |
| ownspout to Ground Yes X No | 5 1 | | |
| eptic Tank Pumped & filled Ye | sK No | | |
| ontractor CAUNGU | | | |
| Special Conditions | | 7 | |
| | | 4 | |
| | | PCO | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |